# **Caulmert Limited**

Engineering, Environmental & Planning Consultancy Services

## **ADRA**

Development at the Former Rhos Street School , Rhos Street, Ruthin

PHASE I GEO-ENVIRONMENTAL DESK STUDY REPORT

#### **Caulmert Limited**

InTec, Parc Menai, Bangor, Gwynedd, LL57 4FG

**Tel:** 01248 672666 **Fax:** 01248 672601

Email: name@caulmert.com
Web: www.caulmert.com

**Document Reference:** 4863-CAU-XX-XX-RP-O-0300

January 2021





#### APPROVAL RECORD

Site: Former Rhos Street School , Rhos Street, Ruthin

Client: Adra

Project Title: Development at the Former Rhos Street School , Rhos Street, Ruthin

Document Title: Phase I and Phase II Geo-Environmental Report

Document Ref: 4863-CAU-XX-XX-RP-O-0300.

Report Status: First Issue

**Project Manager:** Jonathan Sykes

Caulmert Limited: InTec, Parc Menai, Bangor, Gwynedd, LL57 4FG

Tel: 01248 672666

Author	Amy Pritchett	Date	Dec 2020
Reviewer	David Kitching	Date	Jan 2020
Approved	Alan Jones	Date	Jan 2020

#### **DISCLAIMER**

This report has been prepared by Caulmert Limited with all reasonable skill, care and diligence in accordance with the instruction of the above-named client and within the terms and conditions of the Contract with the Client.

The report is for the sole use of the above-named Client and Caulmert Limited shall not be held responsible for any use of the report or its content for any purpose other than that for which it was prepared and provided to the Client.

Caulmert Limited accepts no responsibility of whatever nature to any third parties who may have been made aware of or have acted in the knowledge of the report or its contents.

No part of this document may be copied or reproduced without the prior written approval of Caulmert Limited.

# Former Rhos Street School, Rhos Street, Ruthin

# **TABLE OF CONTENTS**

1.0	INTRODUCTION1
1.1	DETAILS OF COMMISSION
1.2	LIMITATIONS OF THIS STUDY1
1.3	OBJECTIVES OF REPORT1
1.4	SCOPE OF REPORT1
1.5	PREVIOUS INVESTIGATIONS2
2.0	SITE LOCATION AND DESCRIPTION
2.1	SITE LOCATION AND DESCRIPTION
2.2	SITE WALKOVER SURVEY4
2.3	SITE HISTORY5
2.4	GEOLOGY9
2.5	MINING9
2.6	GROUND STABILITY10
2.7	HYDROGEOLOGY & HYDROLOGY10
2.8	GROUND GAS
3.0	INFORMATION FROM THIRD PARTIES11
3.1	ENVIRONMENTAL DATABASE
4.0	PROPOSED DEVELOPMENT
5.0	RISK ASSESSMENT
5.1	INTRODUCTION
5.2	PRELIMINARY CONCEPTUAL SITE MODEL (CSM)
5.3	IDENTIFIED POTENTIAL SOURCES

5.4	QUALITATIVE RISK ASSESSMENT	16
6.0	CONCLUSIONS AND RECOMMENDATIONS	0
6.1	CONCLUSIONS	0
6.2	RECOMMENDATIONS	1

## **FIGURES**

Figure 1 Site Location Plan

Figure 2 Site History – Historical Map Extracts – Figures 2A-F

## **APPENDICES**

**Appendix 1** Site Walkover Photographs

Appendix 2 Envirocheck Report

#### 1.0 INTRODUCTION

#### 1.1 Details of Commission

- 1.1.1 Caulmert Ltd were commissioned by Adra ("the Client") to undertake a geo-environmental appraisal of a site known as the former Rhos Street School, Rhos Street, Ruthin ("the Site").
- 1.1.2 The Site covers an area of 0.55Ha and is currently unused. The Site is being considered for residential development.
- 1.1.3 This report comprises the findings from a desk-based study (using third party information) and a site walkover. Third party information was procured from the following sources:
  - i. A review of an Envirocheck report (Appendix 2), including geological and environmental data.
  - ii. Information obtained from online sources from the British Geological Survey and Natural Resources Wales website.

#### 1.2 Limitations of this Study

- 1.2.1 This report is solely for the use of the Client and should not be relied upon by third parties without prior written consent from Caulmert.
- 1.2.2 Information used within this report has been gathered from data sets compiled by third party organisations and purchased on behalf of the Client. The validity and accuracy of this third-party information is outside the control of Caulmert.
- 1.2.3 Interpretation and recommendations contained within this report should not be assumed valid for adjacent areas of land or alternative land uses and are based upon the proposed layout provided to Caulmert at the time of compiling this report.

# 1.3 Objectives of Report

1.3.1 The objective of this report is to complete an assessment of potential environmental and geotechnical liabilities associated with the proposed redevelopment of the site.

## 1.4 Scope of Report

- 1.4.1 The scope of works consists of the following:
  - A review of third-party information.
  - A site walkover assessment looking a potential geotechnical and environmental risks (internal inspection of the buildings was not available at the time of this investigation);
  - An assessment of potential sources of pollutants on the site and in the immediate surrounding area.

- Derivation of a preliminary conceptual site model (CSM) identifying potential sources, pathways and receptors of contaminants.
- and recommendations for intrusive investigations (as necessary).

# 1.5 Previous Investigations

1.5.1 Caulmert is unaware of any previous investigations or reports linked to this site.

#### 2.0 SITE LOCATION AND DESCRIPTION

#### 2.1 Site Location and Description

- 2.1.1 The Site is located approximately 300m southeast of Ruthin town centre, at National Grid Reference of 312867, 358208 .
- 2.1.2 A Site location plan is provided as Figure 1, with red line boundary around the site area.



Figure 1: Location plan of site with red line boundary

- 2.1.3 The Site is roughly rectangular in shape and occupies an area of 0.55Ha. The Site is accessed from Rhos Street to the north of the site.
- 2.1.4 The boundaries of the Site are defined by residential dwellings to east, Rhos Street and residential dwellings to the north, residential dwellings and hospital car park to the west and Ruthin Community Hospital to the south.
- 2.1.5 The Site area has been developed through the creation of level development platforms within the surrounding sloping ground which has created height differences in the region of c. 0.7m-1.6m(see site walkover photographs in Appendix A for further detail). Therefore, there are a number of retaining walls present onsite.
- 2.1.6 A summary of the Site's current uses, and that of its surroundings, from available information is presented in Table 2.1.

**Table 2.1: Site Description** 

Site Location					
OS Map Reference	312867, 358208				
Site Area	0.55Ha				
Site Setting /	Current Land Use	Unused (former school)			
Description	Surrounding Area	North: Rhos Street and residential housing			
		East: Residential housing and school			
		South: Ruthin Community Hospital			
		West: Residential housing.			

## 2.2 Site Walkover Survey

- 2.2.1 A site walkover survey was completed by a Caulmert Engineer on the 24<sup>th</sup> December 2020. The site walkover comprised of an external inspection of the site and buildings, no access to the buildings was available at the time of this investigation.
- 2.2.2 A summary of the observations made during the site visit are presented in Table 2.2 below. Photographs from the site walkover are included in Appendix 2.

Table 2.2: Summary of Observations from the Site Walkover Survey

Observations	Comments
Buildings and Structures	The main school building occupies the centre of the site and appears to comprise a 19 <sup>th</sup> century stone building with a pitched roof, with a later 20 <sup>th</sup> century extension. A playground surrounds the school building to the south, west and north. A further single storey brick 'community' building is located in the east of the site with a small brick substation. The majority of the site is covered in asphalt hardstanding. A car park is located in the south of the site accessed via an asphalt road in the east. A retaining wall supports the playground above Rhos Street in the north, with three shuttered/boarded 'window' type openings noted, suggesting a basement/under croft feature. No evidence of an access point was noted in the playground.
Topography	The general topography slopes down from east to west by approximately 2m. The site also slopes from the north up to the south by approximately the same. However, the site itself

	is generally level, development platforms have been created and the site is supported by a number of small retaining walls.
Site Access and Security	The site is currently accessed of Rhos Street via a locked gate from a shared access road with the adjacent residential dwellings. The site is generally surrounded by a mixture of low stone walling or wooden fencing. However, temporary 'herras' type security fencing currently secures the site.
Services	A foul drainage system appears to link into the main sewer within Rhos Street along with a surface water drainage system. A substation is located in the east of the site and it is understood that the site is connected to the potable water supply.
Vegetation	Limited vegetation onsite, peripheral grass around car parking.
Invasive Species	None identified.
Surface Water Features	None identified.
Potential Contaminative Sources (on site)	None.
Potential Contaminative Sources (off site)	None.
Other Information	None.

## 2.3 Site History

- 2.3.1 Historical maps from the Ordnance Survey (OS) dating from 1875 to 2020, procured from *Envirocheck* (order number 270678250\_1\_1), were reviewed in compiling this desk study. The maps are presented within the *Envirocheck* report included in Appendix 1, with key extracts presented in Figures 2A-F.
- 2.3.2 The map extract dated 1875, see Figure 2A, shows the site to be part of a school and school playground/playing fields. 40m east is the Union Workhouse. A railway line is positioned c.200m west of the site boundary and a gas works c. 400m north west. The surrounding areas comprise of agricultural fields and residential housing.

January 2021




Figure 2A: Map Extract 1875

2.3.3 By 1900 (Figure 2B), the western end of the school building has had a small extension.




Figure 2B: Map Extract 1900

2.3.4 The 1914 map extract shows a plant nursery to be c.50m north west and a sandpit c.80 north east.




Figure 2C: Map Extract 1914

2.3.5 The 1969 map extract shows a new building along the eastern site boundary that the Ruthin Union Workhouse has been replaced by Ruthin Hospital. An engineering works is present c.100m east and a plant nursery is present c.200m north east. The sand pit 50m north east has been infilled and has a playground overlying it. The gas works to the north west have now gone and have been replaced by a storage depot and offices. Significant housing development has taken place to the north of the site.




Figure 2D: Map Extract 1969

2.3.6 The map extract dated 1975-1984 shows that the school within the site boundary has extended to the south. Ruthin Hospital has also extended to the south.




Figure 2E: Map Extract 1975-1984

2.3.7 No further significant changes have been identified on the remaining historical maps. To view all historical maps, refer to Appendix 1.

**Table 2.3: Potentially Contaminating Land Uses** 

On-site History (activities within the red-line Site boundary)						
Potentially Contaminative Past Uses	Map Date					
	From	То				
Made ground used to raise site level	Unknown	Present				
Made ground construction of school building	Pre 1875	Present				
Non-Contaminative Past Uses						
Playing fields	Pre-1875	Pre 1969				
Primary School	Pre-1875	Present				
Off-site History (activities within 500m of the red-line Site boundary)						
Potentially Contaminative Past Uses						
Construction materials from surrounding buildings and roads	Pre 1875	Present				
Filling in of sand pit	Post 1912	Pre 1969				
Gas Works (later a depot)	Pre 1875	Pre 1994				

## 2.4 Geology

- 2.4.1 The British Geological Survey (BGS) online geological maps (1:50,000) indicates that there is no superficial deposit cover in the area of the site. However, the north of the site is shown as 'Artificial Ground- Made Ground'. It is assumed that this is associated with the creation of the development platforms for the construction of the school.
- 2.4.2 The bedrock underlying the Site is that of the Kinnerton Sandstone Formation, generally consisting of fine to medium grained cross-stratified sandstone (predominantly aeolian). It is likely that this strata has been exploited by the historical sand pit located to the northeast.

#### 2.5 Mining

- 2.5.1 The *Envirocheck* report states that the Site is in an "area that might not be affected by coal mining". There are no coal bearing strata at shallow depth below the site. It is therefore concluded that the risk from historical coal mining is negligible.
- 2.5.2 The *Envirocheck* further states that there is "no hazard" in terms of non-coal mining activity. However, the presence of the 'sand pit' suggests that the Kinnerton Sandstone may have been worked for local building use.

#### 2.6 Ground Stability

2.6.1 The *Envirocheck* report states that there is very low risk of collapsible and compressible ground and no hazard for potential ground dissolution on and around the site boundary. There is no hazard for running sand.

# 2.7 Hydrogeology & Hydrology

- 2.7.1 The nearest mapped surface water feature is the river Clwyd approximately 655m west of the site boundary.
- 2.7.2 The bedrock has been classified as a 'medium vulnerability Principal Aquifer' which has been stated by the Environment Agency as being "layers of rock or drift deposits that have high intergranular and/or fracture permeability meaning they usually provide a high level of water storage. They may support water supply and/or river base flow on a strategic scale. In most cases, principal aquifers are aquifers previously designated as major aquifer".
- 2.7.3 The site is not within a source protection zone.

#### 2.8 Ground Gas

- 2.8.1 There is one historical landfill site within 500m which is located 352m south west of the site. Waste included inert and industrial waste. The last input was 21<sup>st</sup> December 1993. There is significant development (including residential) between the source and the Site and therefore it is unlikely to be a significant ground gas source.
- 2.8.2 The Envirocheck report indicates the Site is in a Lower probability radon area (less than 1% of homes are estimated to be at or above the Action Level). No radon protective measures are necessary in the construction of new dwellings or extensions.

#### 3.0 INFORMATION FROM THIRD PARTIES

#### 3.1 Environmental Database

3.1.1 An *Envirocheck* assessment report was procured (ref: 270678250\_1\_1) and is presented as Appendix 1. The pertinent information from the report is presented in Table 3.1.

**Table 3.1: Summary of Environmental Information** 

Reference	Description				
Agency and Hydrological					
BGS Groundwater Flooding Susceptibility	The site is not within an area with potential for groundwater flooding of property situated below ground level.				
Discharge Consents	There have been 1 discharge consent located within a 500m radius of the Site which is located 361m north west. The discharge type is unknown with the receiving water being an unnamed tributary of the river Clwyd.				
Prosecutions Relating to Controlled Waters (potentially harmful discharges to public sewers)	None recorded within 500m of the Site.				
Local Authority Pollution Prevention and Controls (legislation governing certain industrial activities and their impact on the environment)	There are 3no within 500m of the site boundary which have been associated with  - E.G. Atkinson & CoRhos Street Garage (authorisation revoked) 31m north  - White Bear Garage (authorisation permitted) 156m west  - White Bear Garage (authorisation revoked) 172m south west				
Nearest surface water feature	River Clwyd approximately 655m west				
Pollution Incident to Controlled Waters (National Incident Recording System, List 1 & 2)	None recorded within 500m of the Site.				
Extreme Flooding from Rivers or Sea without Defences	The site is not at risk of extreme flooding from rivers or sea without defences.				

Waste				
Licensed Waste Management and Landfill Sites  Industrial Land Use	None recorded within 500m of the site.  There is one historical landfill site within 500m, located 352m south west of the site. Waste included inert and industrial waste. The last input was 21st December 1993. The site is down gradient of the site and unlikely to be a significant contamination risk to the Site.			
Potentially Contaminative Activities (list of commercial/industrial premises close to site with potential for contamination)	24no. inactive and active industrial land uses have been recorded within a 500m radius of the Site which include industries such as garage services, hospitals, ceramic manufacturers, blacksmiths and forgemasters, hardware, fuel stations, car dealers, dry cleaners etc. For full list please see the industrial land use section of the <i>Envirocheck</i> report in Appendix 2.  However, due to the proximity to site none have been identified as being a significant contamination risk to the Site.			
Hazardous Substances				
COMAH/NIHHS Sites (Dangerous or Hazardous Sites)	None recorded within 500m of the site.			
Explosive Sites	None recorded within 500m of the site.			
Planning Hazardous Substance (consents/enforcements)	None recorded within 500m of the Site.			
Sensitive Land Use				
Designated Environmentally Sensitive Sites	The site is within the Clwydian range which is classified as an 'Environmentally Sensitive Area'.			

#### 4.0 PROPOSED DEVELOPMENT

- 4.1.1 The Site is being considered for residential development. No development layout is currently available however it is understood that the development is likely to comprise Six 2-bed houses (including two affordable) and ten 3-bed houses.
- 4.1.2 No construction details, structural loads or site wide elevations have been received to date. It is assumed the building will be of traditional load bearing masonry wall construction.

#### 5.0 RISK ASSESSMENT

#### 5.1 Introduction

- 5.1.1 Environmental Risk has been addressed by adopting a site-specific, qualitative approach, to identify the risk of environmental harm. The guiding principle of this approach is an attempt to establish connecting links between a hazardous 'source', via an exposure 'pathway', to a potential 'receptor'. This is in accordance with the Department of the Environment, Transport and Regions (DETR) guidance on Contaminated Land and the Construction Industry Research and Information Association.
- 5.1.2 This assessment will identify where pollutant linkages may exist, by considering where a viable pathway may exist, which connects a potential source with a receptor. A pollutant linkage is the term used by the DETR in their standard procedure on risk assessment. If there is no pollutant linkage, then there is no risk.
- 5.1.3 Our risk assessment is based on the redevelopment of the site with a Residential with plant uptake end-use.

## 5.2 Preliminary Conceptual Site Model (CSM)

5.2.1 Contaminated land risk assessment is based on the development of a conceptual model for the site. This is a representation of the relationship between potential contaminant sources, pathways and receptors. A preliminary conceptual site model is based on the inferred ground conditions and environmental data obtained from existing data sources. A conceptual site model is discussed in the following sections.

#### 5.3 Identified Potential Sources

5.3.1 The following potential sources of contamination have been identified from historic uses of the site and surrounding area; potential sources of contamination are summarised below:

#### **On-site Sources**

- 5.3.2 Potential sources of contamination associated with the historical and current activities on the site include:
  - Made Ground located on-site associated with creation of development platforms and construction of the school.
  - Ground gas emanating from Made Ground. No Significant depth of Made Ground anticipated, therefore ground gas risk likely to be low.

# **Offsite Sources**

- 5.3.3 Potential sources of contamination in the immediate site surroundings comprise:
  - Mobile contaminants associated with demolition and redevelopment of the Union Workhouse.
  - Mobile contaminants from former gas works/depot to the northwest.
     Unlikely to be a significant source to subject site which is 'up gradient' of the source'...
  - Ground gas emanating from infilled sand pit to the northeast. Unlikely to be a significant source, given size, location and time since backfilling.

#### Receptors

- 5.3.4 The following receptors have been identified:
  - Future site users.
  - Construction workers during redevelopment works.
  - Controlled Waters (groundwater), Principal aquifer.
  - In ground services and construction materials.

### **Pathways**

- 5.3.5 The following pathways link the potential contaminants with the sensitive receptors:
  - Contact, ingestion and inhalation of contaminated soil and dust.
  - Leaching and migration via soil mass and rock discontinuities.
  - Humans: Ingestion, skin contact, inhalation of dust and outdoor air.
  - Buildings: Direct contact.
  - Buildings: Ingress via permeable soils and/or construction gaps.
  - Underlying groundwater: Migration of leachable contaminants.
  - Plant uptake.
- 5.3.6 The preliminary risk assessment process has identified some potential risks to site demolition and redevelopment workers. However, consideration of occupational health and safety issues is beyond the scope of this report and need to be considered separately in the Construction Phase Health and Safety Plan.

5.3.7 A CSM has been derived from the desk study and site walkover and is presented in Table 5.1.

#### 5.4 Qualitative Risk Assessment

- 5.4.1 A qualitative risk assessment has been undertaken for these potential source-pathway-receptor linkages. This is based on consideration of both:
  - The likelihood of an event (takes into account both the presence of the hazard and receptor and the integrity of the pathway).
  - The severity of the potential consequence (takes into account both the potential severity of the hazard and the sensitivity of the receptor).
- 5.4.2 The risk assessment has been based on development of the site with a proposed Residential with plant up take.

**Table 5.1 Summary of Potential Pollutant Linkages (Conceptual Site Model)** 

Source	Pollutant / Hazard	Receptors	Pathways to Receptor	Associated Hazard [Potential severity]	Likelihood of Occurrence	Potential Risk	
On-site Made Ground - relic foundations, asbestos, demolition rubble	PAH, Heavy metals, Sulphate, Asbestos.	Construction workers Future Site Occupiers	Contact, ingestion, inhalation	Effect on human health [Low-Severe]	Any risks can be mitigated by appropriate site management during construction stage.  Asbestos awareness training and suitable PPE provided for construction staff.  Pre-demolition asbestos survey and appropriate removal prior to demolition further reduce risk.  Any contaminated Made Ground likely to be removed or isolated beneath hardstanding and/or a clean cover system/growing medium minimising risk to future site users.	Low	
		New in ground services and construction materials.	Direct contact	Degradation [Slight]	Any potential risks can be mitigated by use of appropriate construction materials, chemical resistant supply pipes and use of oversized service trenches and clean fill.	Low	
		Controlled Waters Groundwater	Leaching via ground water	Pollution of controlled waters [Slight]	No significant mobile contaminants anticipated however this should be confirmed through intrusive investigations.	Low	
On-site: Ground Gas from Made Ground.	Ground Gas.		Future Site Occupiers	Migration through soils or	Asphyxiation or explosion [Severe]	Limited Made Ground anticipated (generally <1m), and likely to comprise inert type materials with low gas generation potential.	Low
			Buildings	groundwater to indoor air.	Explosion [Severe]	Installation of appropriate ground gas protection measures will mitigate any risk.	Low
Offsite Ground Gas migrating from historic infilled sand pit to the northeast of site.	Ground Gas	Future Site Occupiers	Migration through soils or groundwater.	Asphyxiation or explosion [Severe]	The historic sand pit is small in plan area suggesting limited ground gas generation potential. The site is located 'up gradient' of the Site and therefore ground gas is unlikely to migrate to the site. In addition to this given	Negligible to Low.	
		Buildings	Migration through service trenches,	Explosion [Severe]	the time since backfilling any potential ground gas generation potential should have peaked.	Negligible to Low.	

		Neighbouring Properties	pipework to indoor air.	Asphyxiation or explosion [Severe]		Negligible to Low.
Offsite sources – Historic Gasworks/Depot	Spillages and leaks may have resulted in migration through	Construction workers Future Site Users	Direct contact, inhalation, ingestion	Effect on human health [Moderate to Low]	The site is 'up gradient' from source and a significant distance from site.  Migration of contamination is very unlikely.  Any risks can be mitigated by appropriate site management during construction stage.  Following re-development, the site is likely to be covered by hard surfacing thus minimising risk to future site users.	Negligible to Low
located to the northwest.	ground of inorganic/organic contaminants.	New in ground services and construction materials.	Direct contact	Degradation [Slight]	The site is 'up gradient' from source and a significant distance from site.  Migration of contamination is very unlikely.  Any potential risks can be mitigated by use of appropriate construction materials/ and chemical resistant supply pipes.	Negligible to Low

#### 6.0 CONCLUSIONS AND RECOMMENDATIONS

#### 6.1 Conclusions

- 6.1.1 At this stage, the CSM constitutes a risk assessment which determines only the likelihood of a linkage being present. The preliminary CSM should be refined and revised as more site information is obtained.
- 6.1.2 The identification of a potential pollutant linkage does not necessarily mean that there is a risk, or that the linkage is present, but that further investigation is required to establish whether or not that risk exists. Whereby a risk is identified and verified, the potential consequence of harmful effect and the likelihood of its occurrence should then be established in order to determine whether the risk is acceptable or unacceptable.
- 6.1.3 The preliminary risk assessment undertaken for the site based on existing desk study data has identified:
  - The site is a former (primary education) school, within a principally residential area. The development of the school required cut and fill works due to the sloping topography and therefore some Made Ground is anticipated. The site is not located within a Coal mining area.
  - The school is shown from the earliest OS historical map and appears to have been extended in the late 1980's, but other than that has not significantly changed. The Union Workhouse borders the site to the east, with an infirmary constructed in the early 20<sup>th</sup> century, this later became the Ruthin Community Hospital which still stands today, and the workhouse building became a 'Public Assistance Institute and latterly a 'care home' before its demolition in the 1960's.
  - A small sand pit which was infilled is present to the northeast of the site along
    with an Engineering Works to the east and a former Gas Works/Depot. None
    of these are thought likely to significantly impact the Site. within the former
    garage building -to the immediate north of the current entrance. Three (oil)
    interceptors were also recorded to be located under the site during the site
    walkover.
  - This review has identified the potential for Made Ground placed on site. The nature of Made Ground can be variable and typically comprises reworked site material mixed with demolition waste (potentially including asbestos), furnace or hearth ash, clinker, or material that has previously been imported onto site from an external source. As such any Made Ground may represent a potential source of contamination.
  - The Kinnerton Sandstone is shown to be present at shallow depth below any Made Ground and it is anticipated that standard foundations are likely to be suitable across the majority of the site.

- 6.1.4 Potential on-site sources of contamination associated with previous site uses include the presence of Made Ground.
- 6.1.5 Potential off-site sources of leachable contaminants which could theoretically migrate onto the site via surface or ground waters are likely to be located at a higher elevation/hydraulic gradient than the subject site and are likely to be limited to the infilled sand pit and Engineering Works located to the northeast and east respectively.
- 6.1.6 The potential for ground gas associated with potential on-site and off-site sources including Made Ground is generally low to negligible. No previous gas monitoring data has been obtained and the presence and extent of any ground gas is currently unknown.
- 6.1.7 Given the historical land use of the site and the surrounding area, the perceived risk to the proposed development and the end users from any potential ground contamination is considered to be low. However, this should be confirmed through intrusive investigations.
- 6.1.8 Accordingly, it is recommended that further intrusive site investigations, (including ground gas monitoring) are undertaken prior to the redevelopment of the site, in order to assess any potential risks, and to provide geotechnical information for design purposes.


#### 6.2 Recommendations

- 6.1.9 Building work is regulated under the Building Regulations 1991. Schedule 1 requires 'precautions shall be taken to avoid danger to health and safety caused by substances found on, or in the ground covered by the building'.
- 6.1.10 Given the Residential end-use of the site it is considered that based on the potential contamination sources currently identified, the site generally represents a low hazard both to the end-users and more generally to the wider environment. However, the likelihood of risk and liability cannot be fully determined from the findings of this Phase I environmental review alone, and uncertainty remains with respect to determination of actual risks presented, it is therefore recommended that more detailed analysis of environmental and geotechnical risk and associated liabilities based on site specific data is undertaken designed to:
  - Prove geological succession, presence, depth and thickness of any Made Ground and depth to bedrock.
  - Adequately characterise the nature, degree and extent of potential contamination, with respect to end users, health and safety of workers, and risk to construction materials.
  - Determine Ground Gas concentrations and flow rates to allow appropriate protection measures to be assessed and incorporated into any sub-structural designs.
  - Determine Groundwater levels and groundwater regime.

- Determine indicative geotechnical parameters required for design purposes.
- Determine the extent of the potential basement area identified in the retaining wall along Rhos Street.

#### **REFERENCES**

- [1] DEFRA and Environment Agency (2004). *Model Procedures for the Management of Land Contamination*. R & D Publication CLR 11.
- [2] National House Builders Council, Environment Agency and Chartered Institute of Environmental Health (2008). *Guidance for the Safe Development of Housing on Land Affected by Contamination*. R & D Publication 66.
- [3] DETR Circular 01/2006 (2006). Environmental Protection Act 1990 Part 2A. Contaminated Land.
- [4] British Standard Institution (2001). *Code of Practice for Investigation of Potentially Contaminated Sites.* BS 10175:2001
- [5] British Standards Institution (2010): *Environmental Management Environmental Assessment of Sites and Organisations* (EASO). BS ISO 14015:2010.
- [6] British Standards Institution (2013): *Code of practice for the investigation of potentially contaminated sites*. BS 10175:2011+A1:2013.
- [7] British Standards Institution (2015): *Code of practice for ground investigations*. BS5930:2015.
- [8] Building Research Establishment (2007): *Radon: guidance on protective measures for new dwellings*. BRE Report BR211.
- [9] Department of Food and Rural Affairs (2012). Environmental Protection Act 1990: Part 2A, Contaminated Land Statutory Guidance.
- [10] CIRIA C665:2007 Assessing the risk posed by hazardous ground gases to buildings.
- [11] Environment Agency (2012) 'What's in your backyard?' Wiyby <a href="https://www.environmentagency.gov.uk/wiyby/">www.environmentagency.gov.uk/wiyby/</a>







Rhos Street, School, Ruthin

Photo:

1

# **Site Walkover Photographs:**



Existing site entrance from Rhos Street, with original school building in the background.



# Project: Rhos Street, School, Ruthin

Photo:

2a &2b

# **Site Walkover Photographs:**



Possible historical basement feature within retaining wall along northern boundary (Rhos Street).



Playground above Rhos Street Retaining wall, no evidence of infilled basement, although playground has been resurfaced.



# Project: Rhos Street, School, Ruthin

Photo:

3

**Site Walkover Photographs:** 



Current vehicular access off Rhos Street along eastern boundary of the site, with main school building approximately 1m below road level.




Rhos Street, School, Ruthin

Photo:

4

# **Site Walkover Photographs:**



Electricity Substation in the east of the site.



Rhos Street, School, Ruthin

Photo:

5

# **Site Walkover Photographs:**



Former community building in the east of the site.



Rhos Street, School, Ruthin

Photo:

6

# **Site Walkover Photographs:**



Collapsed paving in the east of the site to the north of the community building.



Rhos Street, School, Ruthin

Photo:

7

# **Site Walkover Photographs:**



Former school car park in the south of the site, currently being used as construction yard/site compound for adjacent hospital refurbishment work.



Rhos Street, School, Ruthin

Photo:

8

# **Site Walkover Photographs:**



Stone retaining wall along eastern boundary, looking north.



Rhos Street, School, Ruthin

Photo:

9

#### **Site Walkover Photographs:**



Playground to the south of the school buildings, part of which is currently being used as construction yard/site compound for adjacent hospital refurbishment work.

Brick retaining wall in the background supporting former school car park.



Rhos Street, School, Ruthin

Photo:

10

#### **Site Walkover Photographs:**



Original school building in the background with modern extension in the foreground. Photo looking northeast from western boundary.



Rhos Street, School, Ruthin

Photo:

11

#### **Site Walkover Photographs:**



Courtyard area between the original school building to the left and newer extension to the right. Steel posts supporting former sun canopy.



Rhos Street, School, Ruthin

Photo:

**12** 

#### **Site Walkover Photographs:**



View from the south across playground to modern extension



Rhos Street, School, Ruthin

Photo:

**13** 

### Site Walkover Photographs:



Concrete retaining wall in the east of the site supporting access road to car park located to the south of the playground.



Rhos Street, School, Ruthin

Photo:

14

**Site Walkover Photographs:** 



Brick retaining wall supporting car park above playground.





### **Envirocheck® Report:**

#### **Datasheet**

#### **Order Details:**

**Order Number:** 

270678250\_1\_1

**Customer Reference:** 

4865

**National Grid Reference:** 

312870, 358200

Slice:

Α

Site Area (Ha):

0.55

Search Buffer (m):

1000

#### **Site Details:**

19, Rhos Street RUTHIN LL15 1DU

#### **Client Details:**

Mr A Jones Caulmert Ltd Unit F13 InTec Parc Menai Bangor Gwynedd LL57 4FG







Report Section	Page Number
Summary	-
Agency & Hydrological	1
Waste	16
Hazardous Substances	-
Geological	20
Industrial Land Use	22
Sensitive Land Use	31
Data Currency	32
Data Suppliers	36
Useful Contacts	37

#### Introduction

The Environment Act 1995 has made site sensitivity a key issue, as the legislation pays as much attention to the pathways by which contamination could spread, and to the vulnerable targets of contamination, as it does the potential sources of contamination.

For this reason, Landmark's Site Sensitivity maps and Datasheet(s) place great emphasis on statutory data provided by the Environment Agency/Natural Resources Wales and the Scottish Environment Protection Agency; it also incorporates data from Natural England (and the Scottish and Welsh equivalents) and Local Authorities; and highlights hydrogeological features required by environmental and geotechnical consultants. It does not include any information concerning past uses of land. The datasheet is produced by querying the Landmark database to a distance defined by the client from a site boundary provided by the client.

In this datasheet the National Grid References (NGRs) are rounded to the nearest 10m in accordance with Landmark's agreements with a number of Data Suppliers.

#### **Copyright Notice**

© Landmark Information Group Limited 2020. The Copyright on the information and data and its format as contained in this Envirocheck® Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, the Environme Agency/Natural Resources Wales and Natural England, and must not be reproduced in whole or in part by photocopying or any other method. The Report is supplied under

Agency/Matural Resolutes waters and Natural England, and mist not be reproduced in whole of in part by protocopying of any other method. The Report is supplied under Landmark's Terms and Conditions accepted by the Customer.

A copy of Landmark's Terms and Conditions can be found with the Index Map for this report. Additional copies of the Report may be obtained from Landmark, subject to Landmark's charges in force from time to time. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and /or other Data providers, whose Copyright material has been included in this Report.

© Environment Agency & United Kingdom Research and Innovation 2020. © Natural Resources Wales & United Kingdom Research and Innovation 2020.

#### Natural England Copyright Notice

Site of Special Scientific Interest, National Nature Reserve, Ramsar, Special Protection Area, Special Conservation Area, Marine Nature Reserve data (derived from Ordnance Survey 1:10000 raster) is provided by, and used with the permission of, Natural England who retain the copyright and Intellectual Property Rights for the data.

#### Scottish Natural Heritage Copyright

Contains SNH information licensed under the Open Government Licence v3.0.

#### Ove Arup Copyright Notice

The Mining Instability data was obtained on licence from Ove Arup & Partners Limited (for further information, contact mining review@arup.com). No reproduction or further use of such Data is to be made without the prior written consent of Ove Arup & Partners Limited. The supplied Mining Instability data is derived from publicly available records and other third party sources and neither Ove Arup & Partners nor Landmark warrant the accuracy or completeness of such information or data.

#### Stantec Copyright Notice

The cavity data presented has been extracted from the PBA (now Stantec UK Ltd) enhanced version of the original DEFRA national cavity databases. Stantec UK Ltd retain the copyright & intellectual property rights in the data. Whilst all reasonable efforts are made to check that the information contained in the cavity databases is accurate we do not warrant that the data is complete or error free. The information is based upon our own researches and those collated from a number of external sources and is continually being augmented and updated by Stantec UK Ltd. In no event shall Stantec UK Ltd or Landmark be liable for any loss or damage including, without limitation, indirect or consequential loss or damage arising from the use of this data.

#### Radon Potential dataset Copyright Notice

Information supplied from a joint dataset compiled by The British Geological Survey and Public Health England.

#### **Natural Resources Wales Copyright Notice**

Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right. Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Some features of this information are based on digital spatial data licensed from the Centre for Ecology & Hydrology © NERC (CEH). Defra, Met Office and DARD Rivers Agency © Crown copyright. © Cranfield University. © James Hutton Institute. Contains OS data © Crown copyright and database right 2020. Land & Property Services © Crown copyright and database right.

#### Report Version v53.0



# **Summary**

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Agency & Hydrological					
BGS Groundwater Flooding Susceptibility	pg 1	Yes	Yes	Yes	n/a
Contaminated Land Register Entries and Notices					
Discharge Consents	pg 1			1	10
Prosecutions Relating to Controlled Waters			n/a	n/a	n/a
Enforcement and Prohibition Notices					
Integrated Pollution Controls					
Integrated Pollution Prevention And Control					
Local Authority Integrated Pollution Prevention And Control					
Local Authority Pollution Prevention and Controls	pg 4		3		7
Local Authority Pollution Prevention and Control Enforcements					
Nearest Surface Water Feature	pg 5				Yes
Pollution Incidents to Controlled Waters	pg 5				8
Prosecutions Relating to Authorised Processes					
Registered Radioactive Substances					
River Quality	pg 7				1
River Quality Biology Sampling Points					
River Quality Chemistry Sampling Points	pg 7				1
Substantiated Pollution Incident Register	pg 7				1
Water Abstractions	pg 8				9 (*8)
Water Industry Act Referrals					
Groundwater Vulnerability Map	pg 12	Yes	n/a	n/a	n/a
Bedrock Aquifer Designations	pg 12	Yes	n/a	n/a	n/a
Superficial Aquifer Designations			n/a	n/a	n/a
Source Protection Zones					
Extreme Flooding from Rivers or Sea without Defences				n/a	n/a
Flooding from Rivers or Sea without Defences				n/a	n/a
Areas Benefiting from Flood Defences				n/a	n/a
Flood Water Storage Areas				n/a	n/a
Flood Defences				n/a	n/a
OS Water Network Lines	pg 12				27



# **Summary**

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Waste					
BGS Recorded Landfill Sites					
Historical Landfill Sites	pg 16			1	2
Integrated Pollution Control Registered Waste Sites					
Licensed Waste Management Facilities (Landfill Boundaries)					
Licensed Waste Management Facilities (Locations)	pg 16				4
Local Authority Landfill Coverage	pg 17	1	n/a	n/a	n/a
Local Authority Recorded Landfill Sites	pg 17				1
Registered Landfill Sites	pg 18				1
Registered Waste Transfer Sites	pg 18				3
Registered Waste Treatment or Disposal Sites					
Hazardous Substances					
Control of Major Accident Hazards Sites (COMAH)					
Explosive Sites					
Notification of Installations Handling Hazardous Substances (NIHHS)					
Planning Hazardous Substance Consents					
Planning Hazardous Substance Enforcements					
Geological					
BGS 1:625,000 Solid Geology	pg 20	Yes	n/a	n/a	n/a
BGS Recorded Mineral Sites					
CBSCB Compensation District			n/a	n/a	n/a
Coal Mining Affected Areas			n/a	n/a	n/a
Mining Instability			n/a	n/a	n/a
Man-Made Mining Cavities					
Natural Cavities					
Non Coal Mining Areas of Great Britain				n/a	n/a
Potential for Collapsible Ground Stability Hazards	pg 20	Yes		n/a	n/a
Potential for Compressible Ground Stability Hazards	pg 20	Yes	Yes	n/a	n/a
Potential for Ground Dissolution Stability Hazards				n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 20	Yes		n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 20	Yes	Yes	n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	pg 20		Yes	n/a	n/a
Radon Potential - Radon Affected Areas			n/a	n/a	n/a
Radon Potential - Radon Protection Measures			n/a	n/a	n/a



### **Summary**

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Industrial Land Use					
Contemporary Trade Directory Entries	pg 22		13	10	77
Fuel Station Entries	pg 30		1		1
Gas Pipelines					
Underground Electrical Cables					
Sensitive Land Use					
Ancient Woodland	pg 31				2
Areas of Adopted Green Belt					
Areas of Unadopted Green Belt					
Areas of Outstanding Natural Beauty					
Environmentally Sensitive Areas	pg 31	1			
Forest Parks					
Local Nature Reserves					
Marine Nature Reserves					
National Nature Reserves					
National Parks					
Nitrate Sensitive Areas					
Nitrate Vulnerable Zones					
Ramsar Sites					
Sites of Special Scientific Interest					
Special Areas of Conservation					
Special Protection Areas					
World Heritage Sites					



Order Number: 270678250\_1\_1

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Limited Potential for Groundwater Flooding to Occur	A13NE (W)	0	1	312874 358195
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Limited Potential for Groundwater Flooding to Occur	A13NW (W)	78	1	312750 358195
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NW (W)	178	1	312650 358195
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NW (NW)	212	1	312650 358350
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Limited Potential for Groundwater Flooding to Occur	A13NW (W)	278	1	312550 358195
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Potential for Groundwater Flooding of Property Situated Below Ground Level	A18SW	389	1	312600
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Limited Potential for Groundwater Flooding to Occur	(NW) A12NE	479	1	358550 312400 358450
	BGS Groundwater I Flooding Type:	Flooding Susceptibility Limited Potential for Groundwater Flooding to Occur	(NW) A12NE (W)	492	1	358450 312350 358350
1	Discharge Consent Operator: Property Type: Location:	s Clwyd County Council Retail Distribution Ruthin Park Rd.Old Station Yard Sit, Park Rd.Old Station Yard Site Ru, Ruthin Craft.	A13NW (NW)	361	2	358350 312620 358530
	Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Natural Resources Wales R Clwyd (Mouth) Cm0087601 1 6th February 1980 6th February 1980 3rd November 1993 Unspecified Not Supplied  Culverted Trib. Of Clwyd Consent expired Located by supplier to within 10m				
2	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Williams M (Engineering) Civil Engineering Lon Parcwr Link Road Rhuthun Natural Resources Wales R Clwyd (Mouth) Cm0146301 1 16th January 1986 16th January 1986 18th February 1993 Unspecified Not Supplied Un Named Trib Of Afon Clwyd Consent expired Located by supplier to within 10m	A18SW (NW)	508	2	312550 358660
3	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Clwyd Fire Service Headquarters Other Transport Ruthin Fire Station Natural Resources Wales R Clwyd (Mouth) Cm0061901 1 14th April 1970 14th April 1970 5th February 1993 Unspecified Not Supplied  Clwyd Consent expired Located by supplier to within 10m	A12NW (W)	686	2	312170 358430



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
4	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status:	Dwr Cymru Cyfyngedig Domestic Property (Multiple) Ruthin Park Rd. & Prior Str. Natural Resources Wales R Clwyd (Mouth) CM0043401 1 13th September 1967 13th September 1967 6th March 2007 Unspecified Freshwater Stream/River  Clwyd Revoked (Water Resources Act 1991, Section 88 & Schedule 10 as amended by Environment Act 1995)	A12NW (W)	693	2	312180 358480
	Positional Accuracy:	Located by supplier to within 100m				
4	Discharge Consent Operator: Property Type: Location:  Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	G & J Greenall Soft Drinks Ruthin Park Road Cambrian Mineral W, Park Road Cambrian Mineral Water, Cambrian Mineral Water Depot Natural Resources Wales R Clwyd (Mouth) Cm0088501 1 16th April 1980 16th April 1980 23rd February 1995 Unspecified Not Supplied  Clwyd Consent expired Located by supplier to within 10m	A12NW (NW)	726	2	312160 358520
5	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Glyndwr District Council Undefined Or Other Ruthin Lon Parcwr Natural Resources Wales R Clwyd (Mouth) Cm0099601 1 17th October 1985 17th October 1985 24th September 1992 Unspecified Not Supplied  Trib. Of A.Clwyd Consent expired Located by supplier to within 10m	A18NW (NW)	743	2	312540 358920
6	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Dwr Cymru Cyfyngedig Sewerage Network - Sewers - Water Company Ruthin 2 Sso In Combined Sewerage S, 2 Sso In Combined Sewerage Sys Natural Resources Wales R Clwyd (Mouth) Cm0017702 1 8th October 1963 8th October 1963 4th March 1994 Unspecified Not Supplied  Clwyd Consent expired Located by supplier to within 100m	A17SW (NW)	814	2	312100 358600



Page 3 of 37

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
7	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water:	Clwyd County Council Undefined Or Other Queen'S Park Primary School-(3 Natural Resources Wales Unknown Cm0003302 1 6th November 1967 6th November 1967 22nd December 1992 Unspecified Not Supplied Gwenfro	A12SW (W)	860	2	312000 358000
	Discharge Consent		A470W	004		040400
8	Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Dwr Cymru Cyfyngedig Sewerage Network - Sewers - Water Company Ruthin Lon Parcwr Fields (2) - Natural Resources Wales R Clwyd (Mouth) CM0199501 1 20th October 1989 20th October 1989 31st August 2000 Unspecified Not Supplied  Clwyd Revoked (Water Resources Act 1991, Section 88 & Schedule 10 as amended by Environment Act 1995) Located by supplier to within 100m	A17SW (NW)	864	2	312100 358700
8	,	Dwr Cymru Cyfyngedig Sewerage Network - Sewers - Water Company Ruthin Lon Parcwr Fields (2) - Natural Resources Wales R Clwyd (Mouth) Cm0017701 1 8th October 1963 8th October 1963 22nd December 1992 Unspecified Not Supplied Clwyd Consent expired Located by supplier to within 100m	A17SW (NW)	864	2	312100 358700
9	Discharge Consent Operator: Property Type: Location:  Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Dwr Cymru Cyfyngedig Sewerage Network - Pumping Station - Water Company Ruthin Land Adj. To Link Road Lon P, Land Adj. To Link Road Lon Parcw, Lon Parcwr Natural Resources Wales R Clwyd (Mouth) Cm0099901 1 17th October 1985 17th October 1985 4th March 1994 Unspecified Not Supplied Trib. Of A.Clwyd Consent expired Located by supplier to within 10m	A17NE (NW)	875	2	312310 358940



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
10	Location:  Prosecution Text:  Prosecution Act: Hearing Date: Verdict: Fine: Cost:	ing to Controlled Waters  Lon Parcwr Industrial Estate, Lon Parcwr Industrial Estate, RUTHIN, Clwyd, LL15 1NJ Using Site Borehole To Extract Water For Use In Soft Drink Production Without License. Wra91 S24(1a) 7th May 2002 Guilty 250 252 Manually positioned within the geographical locality	A17NE (NW)	791	4	312466 358938
11	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Lution Prevention and Controls  E.G. Atkinson & CoRhos Street Garage Rhos Street, RUTHIN, Denbighshire, LL15 1DU Denbighshire County Council, Environmental Health Department GDC/W008/EPA Not Supplied Local Authority Air Pollution Control PG1/1Waste oil burners, less than 0.4MW net rated thermal input Authorisation revoked Automatically positioned to the address	A13NE (N)	31	3	312884 358278
12	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Iution Prevention and Controls  White Bear Garage Llanfair Road, Leading into Wrexham Road, RUTHIN, Clwyd, LL15 1BU Denbighshire County Council, Environmental Health Department DCC/PPC/1.1/040.0 17th May 1993 Local Authority Pollution Prevention and Control PG1/1Waste oil burners, less than 0.4MW net rated thermal input Permitted Automatically positioned to the address	A13SW (W)	156	3	312694 358152
13	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Iution Prevention and Controls  D.T. WilliamsWern Garage Llanfair Road, Ruthin, Denbighshire, Ll15 1bu Denbighshire County Council, Environmental Health Department GDC/W007/EPA Not Supplied Local Authority Air Pollution Control PG1/1Waste oil burners, less than 0.4MW net rated thermal input Authorisation revoked Located by supplier to within 100m	A13SW (SW)	172	3	312700 358100
14	Local Authority Pol Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	lution Prevention and Controls  J T Williams Castle Works, Mill Street, RUTHIN, Denbighshire, LL15 1HT Denbighshire County Council, Environmental Health Department GDC/W009/EPA Not Supplied Local Authority Air Pollution Control PG1/1Waste oil burners, less than 0.4MW net rated thermal input Authorisation revoked Located by supplier to within 100m	A12SE (W)	642	3	312200 358100
15	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Iution Prevention and Controls  Gunn Jcb Ltd  Celtic Works, Lon Parcwr Industrial Estate, Ruthin, Denbighshire, LI15 1ly Denbighshire County Council, Environmental Health Department DCC/PPC/1.1/063.0  Not Supplied Local Authority Pollution Prevention and Control PG1/1Waste oil burners, less than 0.4MW net rated thermal input Permitted  Manually positioned to the address or location	A17SE (NW)	697	3	312335 358728
16	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Iution Prevention and Controls  Rpc Concrete Solutions Quarryfields, RUTHIN, Clwyd, LL15 2UG Denbighshire County Council, Environmental Health Department DCC/PPC/3.1/033.0  18th March 1993 Local Authority Air Pollution Control PG3/1Blending, packing, loading and use of bulk cement Authorisation has varied Manually positioned to the address or location	A12NW (NW)	700	3	312190 358523



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
16	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	lution Prevention and Controls  Tarmac Structural Concrete Ltd Quarryfields, RUTHIN, Denbighshire, LL15 2UG Denbighshire County Council, Environmental Health Department Not Given Not Supplied Local Authority Air Pollution Control PG3/1Blending, packing, loading and use of bulk cement Authorisation revoked Manually positioned to the address or location	A12NW (NW)	700	3	312190 358523
17	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Robert Hunter & Son Lon Parcwr, RUTHIN, Denbighshire, LL15 1NA Denbighshire County Council, Environmental Health Department DCC/PPC/3.5/030.0 27th May 1993 Local Authority Air Pollution Control PG3/15 Mineral drying and roadstone coating processes Authorisation has varied Manually positioned to the address or location	A17SE (NW)	733	3	312445 358860
18	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Iution Prevention and Controls  Malthurst Retail Ltd Park Road, RUTHIN, LL15 1NB Denbighshire County Council, Environmental Health Department DCC/PPC/1.2/004.0 2nd February 1999 Local Authority Pollution Prevention and Control PG1/14 Petrol filling station Permitted Automatically positioned to the address	A12SW (W)	780	3	312051 358173
19	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	Iution Prevention and Controls  Rmf Autocentre Ltd Unit 13-14, Turner Trading Estate, Hen Lon Parcwr, Ruthin, Denbighshire, L115 1na Denbighshire County Council, Environmental Health Department DCC/PPC/1.1/064.0 Not Supplied Local Authority Pollution Prevention and Control PG1/1Waste oil burners, less than 0.4MW net rated thermal input Permitted Manually positioned to the address or location	A17SE (NW)	818	3	312224 358787
	Nearest Surface Wa	ater Feature	A12NW (W)	655	-	312182 358345
20	Property Type: Location: Authority: Pollutant: Note: Incident Date: Incident Reference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	to Controlled Waters  Not Given Texaco Garage, Park Road, RUTHIN Environment Agency, Welsh Region Sewage - Treated Effluent Not Supplied 13th January 1995 22308 Not Given Not Given Unknown Category 3 - Minor Incident Located by supplier to within 100m	A12NE (W)	553	4	312300 358400
21	Property Type: Location: Authority: Pollutant: Note: Incident Date: Incident Reference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	to Controlled Waters  Not Given Ruthin Weir, RUTHIN Environment Agency, Welsh Region Oils - Diesel (Including Agricultural) Poor Management Control 7th October 1996 30167 Not Given Not Given Direct Discharge Category 3 - Minor Incident Located by supplier to within 100m	A12NE (NW)	675	4	312205 358495



Order Number: 270678250\_1\_1

# **Agency & Hydrological**

Page 6 of 37

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
21	Location: Authority: Pollutant: Note: Incident Date: Incident Paference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	o Controlled Waters  Not Given Ruthin Weir, RUTHIN Environment Agency, Welsh Region Coal Solids Poor Management Control 7th October 1996 30167 Not Given Not Given Direct Discharge Category 3 - Minor Incident Located by supplier to within 100m	A12NE (NW)	679	4	312205 358505
21	Location: Authority: Pollutant: Note: Incident Date: Incident Paference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	Not Given Ruthin Weir, RUTHIN Environment Agency, Welsh Region Miscellaneous - Fire water / Foam Poor Management Control 8th October 1996	A12NE (NW)	680	4	312200 358495
21	Location: Authority: Pollutant: Note: Incident Date: Incident Reference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	o Controlled Waters  Water Company Sewage: Storm Overflow RUTHIN Environment Agency, Welsh Region Contaminated Groundwater Blocked Sewer 7th September 1995 25818 Not Given Not Given Overflow Category 3 - Minor Incident Located by supplier to within 100m	A12NE (NW)	682	4	312200 358500
22	Location: Authority: Pollutant: Note: Incident Date: Incident Reference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	Water Company Sewage: Storm Overflow Down Stream Of Ruthin Weir Environment Agency, Welsh Region Natural Foam Weather 12th November 1994	A17SE (NW)	726	4	312200 358600
23	Location: Authority: Pollutant: Note: Incident Date: Incident Reference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	o Controlled Waters  Miscellaneous Premises: Surface Runoff Trelyn Park, Fluer De Lys Environment Agency, Welsh Region Crude Sewage Not Supplied 2nd April 1996 27736 Not Given Not Given Unknown Category 3 - Minor Incident Located by supplier to within 100m	A12SW (W)	733	4	312100 358150
24	Location: Authority: Pollutant: Note: Incident Date: Incident Paference: Catchment Area: Receiving Water: Cause of Incident: Incident Severity:	o Controlled Waters  Not Given RUTHIN Environment Agency, Welsh Region Unknown Weather 28th June 1996 29109 Not Given Not Given Effluent Discharge Category 3 - Minor Incident Located by supplier to within 100m	A17NW (NW)	986	4	312100 358900



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	River Quality				_	
	Name: GQA Grade: Reach: Estimated Distance	Clwyd River Quality A O/F Ruthin Stw -Conf.Afon Hesbin 5.3	A12NE (W)	601	4	312241 358370
	(km): Flow Rate: Flow Type: Year:	Flow less than 2.5 cumecs River 2000				
	River Quality Chem	istry Sampling Points				
25	Name: Reach: Estimated Distance: Objective: Positional Accuracy: Year: GQA Grade: Compliance: Year:	Not Supplied Located by supplier to within 10m 1990 River Quality Chemistry GQA Grade A - Very Good Not Supplied 1993	A12SW (W)	761	4	312070 358160
	GQA Grade: Compliance: Year: GQA Grade: Compliance:	River Quality Chemistry GQA Grade A - Very Good Not Supplied 1994 River Quality Chemistry GQA Grade A - Very Good Not Supplied				
	Year: GQA Grade: Compliance: Year: GQA Grade:	1995 River Quality Chemistry GQA Grade A - Very Good Not Supplied 1996 River Quality Chemistry GQA Grade A - Very Good				
	Compliance: Year: GQA Grade: Compliance: Year:	Not Supplied 1997 River Quality Chemistry GQA Grade A - Very Good Not Supplied 1998				
	GQA Grade: Compliance: Year: GQA Grade: Compliance:	River Quality Chemistry GQA Grade A - Very Good Not Supplied 1999 River Quality Chemistry GQA Grade A - Very Good Not Supplied				
	Year: GQA Grade: Compliance: Year:	2000 River Quality Chemistry GQA Grade A - Very Good Not Supplied 2001				
	GQA Grade: Compliance: Year: GQA Grade: Compliance:	River Quality Chemistry GQA Grade A - Very Good Not Supplied 2002 River Quality Chemistry GQA Grade A - Very Good Not Supplied				
	Year: GQA Grade: Compliance: Year:	2003 River Quality Chemistry GQA Grade A - Very Good Not Supplied 2004				
	GQA Grade: Compliance: Year: GQA Grade: Compliance:	River Quality Chemistry GQA Grade A - Very Good Not Supplied 2005 River Quality Chemistry GQA Grade A - Very Good Not Supplied				
	Year: GQA Grade: Compliance: Year: GQA Grade:	2006 River Quality Chemistry GQA Grade A - Very Good Not Supplied 2007 River Quality Chemistry GQA Grade A - Very Good				
	Compliance: Year: GQA Grade: Compliance:	Not Supplied 2008 River Quality Chemistry GQA Grade A - Very Good Not Supplied				
	Year: GQA Grade: Compliance:	2009 River Quality Chemistry GQA Grade A - Very Good Not Supplied				
		ntion Incident Register				
26	Authority: Incident Date: Incident Reference: Water Impact: Air Impact: Land Impact:	Natural Resources Wales 23rd August 2020	A12SW (W)	819	2	312047 357989



Page 8 of 37

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
27	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Cabana Soft Drinks (North Wales) Ltd 24/66/1/0042 Not Supplied Location Description Not Available Environment Agency, Welsh Region Food And Drink: Water Bottling Not Supplied Groundwater 104 27276 Not Supplied Located by supplier to within 100m	A18NW (NW)	771	4	312540 358950
28	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Glyndwr District Council 24/66/1/0034 100 River Clwyd Environment Agency, Welsh Region Amenity: Lake And Pond Throughflow Water may be abstracted from a single point Surface Not Supplied Not Supplied River Clwyd 01 January 31 December 12th June 1974 Not Supplied Located by supplier to within 100m	A12SW (W)	813	4	312070 357940
28	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Denbighshire County Council 24/66/1/0034 101 River Clwyd Natural Resources Wales Amenity: Lake And Pond Throughflow Water may be abstracted from a single point Surface Not Supplied Not Supplied Not Supplied O1 January 31 December 1st April 1996 Not Supplied Located by supplier to within 10m	A12SW (W)	817	2	312070 357930
28	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Denbighshire County Council 24/66/1/0034 Not Supplied Recreational Pond At Cae Ddol Ruthin Natural Resources Wales Amenity: Lake And Pond Throughflow Water may be abstracted from a single point Surface Not Supplied Not Supplied Not Supplied O1 January 31 December Not Supplied Not Supplied Not Supplied Located by supplier to within 10m	A12SW (W)	817	2	312070 357930



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
29	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Mr I T Jones 24/66/1/0002 Not Supplied Location Description Not Available Environment Agency, Welsh Region Agriculture (General) Not Supplied Well And Borehole Not Supplied Located by supplier to within 100m	A7SE (SW)	923	4	312370 357372
29	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Mr I Jones 24/66/1/0002 100 Well Environment Agency, Welsh Region General Farming And Domestic Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Not Supplied O1 January 31 December 31st December 1965 Not Supplied Located by supplier to within 100m	A7SE (SW)	924	4	312370 357371
30	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Miss C Chamberlin 24/66/1/0004 100 Borehole Environment Agency, Welsh Region General Farming And Domestic Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Not Supplied 01 January 31 December 31st December 1986 Not Supplied Located by supplier to within 100m	A8SE (S)	955	4	313050 357200
31	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Mr P Williams 24/66/1/0053 1 45m Deep Borehole, 116mm Dia. Sherwood Sandstone Environment Agency, Welsh Region General Farming And Domestic Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Not Supplied Not Supplied 1 January 31 December 24th April 2002 Not Supplied Located by supplier to within 10m	A9NE (SE)	987	4	313700 357550



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
31	Water Abstractions Operator:	Mr P Williams	A9NE	987	4	313700
	-	24/66/1/0048 100 45m Deep Borehole, 116mm Dia. Sherwood Sandstone Environment Agency, Welsh Region General Farming And Domestic Water may be abstracted from a single point Groundwater Not Supplied Not Supplied 45M Deep Borehole 116Mm Diameter Sherwood Sandstone 01 January 31 December 29th April 1997 Not Supplied Located by supplier to within 100m	(SE)			357550
	Water Abstractions					
	Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Dwr Cymru Cyfyngedig 24/66/1/0040 100 Borehole 130 Metres Deep Natural Resources Wales Water Supply Related: Transfer Between Sources Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Borehole 130 Metres Deep 01 January 31 December 1st April 2006 Not Supplied Located by supplier to within 100m	A22SW (NW)	1317	2	312160 359370
	Water Abstractions					
	-	Dwr Cymru Cyfyngedig 24/66/1/0040 Not Supplied Ruthin Augmentation Borehole (To River Clwyd) Natural Resources Wales Water Supply Related: Transfer Between Sources Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Not Supplied Not Supplied 101 January 11 December Not Supplied Not Supplied Not Supplied Not Supplied Located by supplier to within 10m	A22SW (NW)	1317	2	312160 359370
	Water Abstractions					
	Operator: Licence Number: Permit Version: Location: Authority: Abstraction:  Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Ruthin Farmers Auction Co Ltd 24/66/1/0045 100 Borehole Natural Resources Wales Other Industrial/Commercial/Public Services: General Washing/Process Washing Water may be abstracted from a single point Groundwater Not Supplied Not Supplied As Above 01 January 31 December 1st April 2008 Not Supplied Located by supplier to within 100m	A16SE (NW)	1338	2	311620 358810



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Ruthin Farmers Auction Co Ltd 24/66/1/0045 Not Supplied Borehole At Ruthin Farmers Market Natural Resources Wales Other Industrial/Commercial/Public Services: General Washing/Process Washing Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Not Supplied O1 January 31 December Not Supplied Not Supplied Not Supplied Not Supplied Not Supplied Located by supplier to within 10m	A16SE (NW)	1338	2	311620 358810
	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Dwr Cymru Cyfyngedig 24/66/1/0041 100 Efail Newydd Borehole Natural Resources Wales Public Water Supply: Potable Water Supply - Direct Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Efail Newydd Borehole 01 January 31 December 1st April 2004 Not Supplied Located by supplier to within 100m	A10SW (SE)	1401	2	314100 357400
	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Dwr Cymru Cyfyngedig 24/66/1/0041 100 Efail Newydd Borehole Natural Resources Wales Water Supply Related: Transfer Between Sources Water may be abstracted from a single point Groundwater Not Supplied Not Supplied Not Supplied 01 January 31 December 1st April 2004 Not Supplied Located by supplier to within 100m	A10SW (SE)	1401	2	314100 357400
	Water Abstractions Operator: Licence Number: Permit Version: Location: Authority: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised Start: Authorised Start: Authorised End: Permit Start Date: Permit End Date: Positional Accuracy:	Dwr Cymru Cyfyngedig 24/66/1/0041 Not Supplied Efail Newydd Borehole For Public Water Supply Natural Resources Wales Public Water Supply: Potable Water Supply - Direct Water may be abstracted from any point within an area Groundwater Not Supplied Not Supplied Not Supplied 01 January 31 December Not Supplied Not Supplied Not Supplied Not Supplied Not Supplied Not Supplied Located by supplier to within 100m	A10SW (SE)	1401	2	314100 357400



Page 12 of 37

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Licence Number: Permit Version: Location: Authority: Abstraction: Abstraction Type: Source: Daily Rate (m3): Yearly Rate (m3): Details: Authorised End: Permit Start Date: Permit End Date:	Dwr Cymru Cyfyngedig 24/66/1/0041 Not Supplied Efail Newydd Borehole For Public Water Supply Natural Resources Wales Water Supply Related: Transfer Between Sources Water may be abstracted from any point within an area Groundwater Not Supplied Not Supplied Not Supplied O1 January 31 December Not Supplied Not Supplied Not Supplied Not Supplied	A10SW (SE)	1401	2	314100 357400
	Classification: Combined Vulnerability: Combined Aquifer: Pollutant Speed: Bedrock Flow: Dilution: Baseflow Index: Superficial Patchiness: Superficial Thickness:	ability Map Principle Bedrock Aquifer - Medium Vulnerability Medium  Productive Bedrock Aquifer, No Superficial Aquifer Intermediate Intergranular 300-550 mm/year >70% <90%  3-10m  High	A13NE (W)	0	2	312874 358195
	Bedrock Aquifer Des Aquifer Designation:	<u>-</u>	A13NE (W)	0	2	312874 358195
	None	om Rivers or Sea without Defences				
	None Areas Benefiting fro	s or Sea without Defences m Flood Defences				
	None Flood Water Storage None	Areas				
32	Watercourse Name: Catchment Name:	Inland river 1147.0 On ground surface True	A12NW (W)	659	5	312178 358344
33	Watercourse Name: Catchment Name:	Inland river 772.5 On ground surface True	A14NW (NE)	691	5	313521 358519
34	Watercourse Name: Catchment Name:	Inland river 17.0 On ground surface True	A12SW (W)	761	5	312072 358145



Page 13 of 37

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
35	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A12SW (W)	774	5	312058 358156
36	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Afon Clwyd Catchment Name: Clwyd Primacy: 1	A12SW (W)	774	5	312058 358156
37	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 122.2  Watercourse Level: On ground surface Permanent: True Watercourse Name: Afon Clwyd Catchment Name: Clwyd Primacy: 1	A12SW (W)	778	5	312056 358141
38	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Afon Clwyd Catchment Name: Clwyd Primacy: 1	A12SW (W)	800	5	312080 357951
39	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	816	5	312421 357466
40	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 15.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Afon Clwyd Catchment Name: Clwyd Primacy: 1	A12SW (W)	825	5	312033 358013
41	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 2.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Afon Clwyd Catchment Name: Clwyd Primacy: 1	A12SW (W)	825	5	312034 358011
42	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 32.3  Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A12SW (W)	826	5	312028 358027
43	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7NE (SW)	842	5	312249 357580



Page 14 of 37

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
44	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7NE (SW)	842	5	312249 357580
45	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 295.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Afon Clwyd Catchment Name: Clwyd Primacy: 1	A7NE (SW)	845	5	312240 357587
46	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: Vunderground Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	849	5	312336 357490
47	OS Water Network Lines  Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	853	5	312329 357492
48	OS Water Network Lines  Watercourse Form: Lake Watercourse Length: 33.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A12SW (W)	857	5	312001 358010
49	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 4.2 Watercourse Level: Underground Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	876	5	312290 357494
50	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 1.0 Watercourse Level: Underground Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	879	5	312286 357494
51	OS Water Network Lines  Watercourse Form: Inland river Watercourse Length: 130.7 Watercourse Level: Underground Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	880	5	312286 357493
52	OS Water Network Lines  Watercourse Form: Lake Watercourse Leenl: 75.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 2	A12SW (W)	882	5	311983 357982



Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
53	OS Water Network Lines  Watercourse Form: Lake Watercourse Length: 67.2 Watercourse Level: On ground surface True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A12SW (W)	882	5	311983 357982
54	OS Water Network Lines Watercourse Form: Inland river	A12SW	936	5	311935
34	Watercourse Length: 349.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	(W)	930	3	357954
	OS Water Network Lines				
55	Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Ciwyd Primacy: 1	A17NE (NW)	937	5	312270 358987
	OS Water Network Lines				
56	Watercourse Form: Inland river Watercourse Length: 16.9 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	958	5	312311 357371
	OS Water Network Lines				
57	Watercourse Form: Inland river Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	959	5	312336 357352
	OS Water Network Lines				
58	Watercourse Form: Inland river Watercourse Level: Underground Permanent: True Watercourse Name: Not Supplied Catchment Name: Clwyd Primacy: 1	A7SE (SW)	960	5	312331 357354





Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Historical Landfill S	Sites				
59	Licence Holder: Location: Name: Operator Location: Boundary Accuracy: Provider Reference: First Input Date: Last Input Date: Specified Waste Type: EA Waste Ref: Regis Ref: WRC Ref: BGS Ref: Other Ref:		A8NW (SW)	352	2	312682 357850
	Historical Landfill S	ites				
60	Licence Holder: Location: Name: Operator Location: Boundary Accuracy: Provider Reference: First Input Date: Last Input Date: Specified Waste Type: EA Waste Ref: Regis Ref: WRC Ref: BGS Ref: Other Ref:		A8NW (S)	579	2	312764 357573
	Historical Landfill S	lites				
61	Licence Holder: Location: Name: Operator Location: Boundary Accuracy: Provider Reference: First Input Date: Last Input Date: Specified Waste Type: EA Waste Ref: Regis Ref: WRC Ref: BGS Ref: Other Ref:	EAHLD14203 31st December 1944 17th November 1994 Deposited Waste included Inert, Industrial, Commercial, Household and Special Waste 0 Not Supplied 6830/0028 Not Supplied NOW-302-L, L/1/29, L/1/33	A18NW (N)	892	2	312561 359088
	Licensed Waste Ma	nagement Facilities (Locations)				
62	Licence Number: Location:  Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference: Positional Accuracy:	BP3794FA Min Y Clwyd Yard, Lon Parcwr, Ruthin, Denbighshire, Denbighshire, LL15 1NA 1 T Williams Company Ltd Not Supplied Natural Resources Wales Household, Commercial And Industrial Transfer Stations Effective 30th August 2017 Not Supplied Located by supplier to within 10m	A17NE (NW)	837	2	312289 358875





Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Licensed Waste Ma	nagement Facilities (Locations)				
62	Licence Number: Location: Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference: Positional Accuracy:	37018 Min Y Clwyd, Lon Parcwr, Ruthin, LL15 1NA I T Williams Company Ltd Not Supplied Natural Resources Wales Household, Commercial And Industrial Transfer Stations Issued 12th November 1994 Not Supplied Located by supplier to within 10m	A17NE (NW)	837	2	312289 358875
63	Licence Number: Location: Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference:	Inagement Facilities (Locations)  104715 Min Y Clwyd, Hen Lon Parcwr, Ruthin, LL15 1NA I T Williams Co Ltd Not Supplied Natural Resources Wales Treatment of waste to produce soil <75,000 tpy Issued 3rd October 2012 Not Supplied Located by supplier to within 10m	A17SW (NW)	911	2	312140 358832
63	Licence Number: Location: Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference:	LB3135AL IT Williams Ltd, Min Y Clwyd, Ruthin, Denbighshire, Denbighshire, LL15 1NA IT Williams Co Ltd Not Supplied Natural Resources Wales Treatment of waste to produce soil <75,000 tpy Effective 3rd October 2012 Not Supplied Located by supplier to within 10m	A17SW (NW)	911	2	312140 358832
	Local Authority Lan Name:	ndfill Coverage  Denbighshire County Council  - Has supplied landfill data		0	3	312874 358195
64	Location: Reference: Authority: Last Reported Status: Types of Waste: Date of Closure:	Corded Landfill Sites  Lon Parcwr, Ruthin  Not Supplied  Denbighshire County Council, Environmental Health Department  Closed  Municipal, Inert, Commercial  Not Supplied  Positioned by the supplier  Moderate	A18NW (N)	906	3	312561 359103





Licence Reference: Licence Easting: 3 Licence Easting: 3 Licence Northing: 3 Operator Location: M Authority: Esite Category: Limber Max Input Rate: U Waste Source Restrictions: Status: Lipated: 1: Preceded By N Licence: Superseded By N Licence: Positional Accuracy: M Boundary Accuracy: M Authorised Waste Ir  Registered Waste Trai	Tudor Williams L/1/ 5 Rear Of Castle Park Estate, Ruthin, Clwyd 312770 357500 Min-Y-Clwyd, Lon Parcwr, Ruthin, Clwyd Environment Agency Wales, North Area Landfill Undefined No known restriction on source of waste  Licence lapsed/cancelled/defunct/not applicable/surrenderedCancelled 1st November 1988 Not Given  Not Given  Manually positioned to the address or location Not Applicable Inert Waste	A8SW (S)	650	4	312770 357500
Boundary Accuracy: N Authorised Waste Ir Registered Waste Trai 66 Licence Holder: I Licence Reference: N Site Location: N Operator Location: N	Not Applicable Inert Waste				
66 Licence Holder: I Licence Reference: N Site Location: N Operator Location: N					
Site Cafegory: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence: Positional Accuracy: Boundary Quality: Authorised Waste  A  B  C  C  C  C  C  C  C  C  C  C  C  C	NOW-317-L (L/1/13) Min-Y-Clwyd Yard, Lon Parcwr, Ruthin, Clwyd Min-Y-Clwyd, Lon Parcwr, Ruthin, Clwyd Environment Agency Wales, North Area Transfer Small (Equal to or greater than 10,000 and less than 25,000 tonnes per year) Some restriction on source of waste  Operational as far as is knownOperational 1st June 1997 NOW-317-L (L/1/13)  Not Given  Manually positioned to the address or location Not Supplied Aluminium, Brass, Copper, Gold, Tin, Zinc Ash, Clinker Brickwork, Builders Rubble, Hardcore Bush, Tree, Garden/Hortic'L Waste Cardboard/Fibreboard/Paper(Inc.Oil/Tar Cement (Set), Concrete Ceramics, Enamels, Glass, Mica/Abras, Pott Chalk, China Clay, Gravel, Hassocks, Stone Coal/Coke Cork Empty Containers Excav.Road Metal (Well Weathered) Iron, Steel Max. Storage In Licence Max. Waste Permitted By Licence Non-Special H'Hold/Com/Ind. Comprising Non-Toxic Adhesive Wastes Non-Toxic Adhesive Wastes Non-Toxic Floor Sweepings. Sweepings) Plasterboard/Plaster Plastics Ragstone, Sub/Topsoil Rubber/Latex Sand, Clean Foundry/Moulding Sand, Silic Shotblast Residue Wood Incl. Sawdust Wood/Wood Prods(Hard/Chipboard) Incinerator Residues Poisonous, Noxious, Polluting Wastes	A17NE (NW)	881	4	312250 358900





Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Registered Waste T	ransfer Sites				
66	Licence Holder: Licence Reference: Site Location: Operator Location: Authority: Site Category: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence:	ransfer Sites  I T Williams & Co Ltd NOW-317-L (L/1/13) Min-Y-Clwyd Yard, Lon Parcwr, Ruthin, Clwyd Min-Y-Clwyd, Lon Parcwr, Ruthin, Clwyd Environment Agency Wales, North Area Transfer Small (Equal to or greater than 10,000 and less than 25,000 tonnes per year) Some restriction on source of waste  Record supersededSuperseded 1st June 1996 NOW-317-L (L/1/13)  NOW-317-L (L/1/13)  Manually positioned to the address or location Not Supplied Aluminium, Brass, Copper, Gold, Tin, Zinc Ash, Clinker Bonded/Cement Asbestos Brickwork, Builders Rubble, Hardcore Bush, Tree, Garden/Hortic'L Waste Cardboard/Fibreboard/Paper(Inc.Oil/Tar Cement (Set), Concrete Ceramics, Enamels, Glass, Mica/Abras, Pott Chalk, China Clay, Gravel, Hassocks, Stone Coal/Coke Cork Empty Containers Excav. Road Metal (Well Weathered) Iron, Steel Max. Storage In Licence Max. Waste Permitted By Licence Non-Special HHold/Com/Ind. Comprising Non-Toxic Adhesive Wastes Non-Toxic Floor Sweepings. Sweepings) Plasterboard/Plaster Plastics Ragstone, Sub/Topsoil Rubber/Latex Sand, Clean Foundry/Moulding Sand, Silic Shotblast Residue Wood Incl. Sawdust Wood/Wood Prods(Hard/Chipboard) Incinerator Residues Poisonous, Noxious, Polluting Wastes	A17NE (NW)	881	4	312250 358900
		Waste N.O.S.				
66	Site Location: Operator Location: Authority: Site Category: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence:	1111 11 1	A17NE (NW)	881	4	312250 358900





Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS 1:625,000 Solid Geology		_		
	Description: Permian Rocks (Undifferentiated)	A13NE (W)	0	1	312874 358195
	Coal Mining Affected Areas				
	In an area that might not be affected by coal mining				
	Non Coal Mining Areas of Great Britain No Hazard				
	Potential for Collapsible Ground Stability Hazards				
	Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (W)	0	1	312874 358195
	Potential for Compressible Ground Stability Hazards	(**)			336193
	Hazard Potential: Very Low	A13NE	0	1	312874
	Source: British Geological Survey, National Geoscience Information Service	(W)			358195
	Potential for Compressible Ground Stability Hazards  Hazard Potential: No Hazard  Source: British Geological Survey, National Geoscience Information Service	A13NW (NW)	0	1	312870 358206
	Potential for Compressible Ground Stability Hazards	, ,			
	Hazard Potential: Very Low British Geological Survey, National Geoscience Information Service	A13SW (SW)	43	1	312821 358144
	Potential for Compressible Ground Stability Hazards				
	Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (E)	225	1	313117 358276
	Potential for Compressible Ground Stability Hazards				
	Hazard Potential: Moderate Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	233	1	312633 358100
	Potential for Ground Dissolution Stability Hazards	(**)			000100
	Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NE (W)	0	1	312874 358195
	Potential for Landslide Ground Stability Hazards				
	Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NE (W)	0	1	312874 358195
	Potential for Running Sand Ground Stability Hazards	(**)			
	Hazard Potential: Very Low	A13NE	0	1	312874
	Source: British Geological Survey, National Geoscience Information Service	(W)			358195
	Potential for Running Sand Ground Stability Hazards  Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (NW)	0	1	312870 358206
	Potential for Running Sand Ground Stability Hazards				
	Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	43	1	312821 358144
	Potential for Running Sand Ground Stability Hazards	(377)			330144
	Hazard Potential: Very Low	A13NW	141	1	312688
	Source: British Geological Survey, National Geoscience Information Service	(W)			358214
	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low	A13NE	225	1	313117
	Source: British Geological Survey, National Geoscience Information Service	(E)	223	ľ	358276
	Potential for Running Sand Ground Stability Hazards				
	Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (W)	235	1	312591 358226
	Potential for Shrinking or Swelling Clay Ground Stability Hazards	(**)			
	Hazard Potential: No Hazard	A13NE	0	1	312874
	Source: British Geological Survey, National Geoscience Information Service	(W)			358195
	Potential for Shrinking or Swelling Clay Ground Stability Hazards  Hazard Potential: Very Low	A13NW	141	1	312688
	Source: British Geological Survey, National Geoscience Information Service	(W)			358214
	Potential for Shrinking or Swelling Clay Ground Stability Hazards	A4001A1	000	,	040005
	Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (W)	233	1	312633 358100
	Radon Potential - Radon Affected Areas				
	Affected Area: The property is in a Lower probability radon area (less than 1% of homes are estimated to be at or above the Action Level).  Source: British Geological Survey, National Geoscience Information Service	A13NE (W)	0	1	312874 358195



# **Geological**

ap D	Details		Estimated Distance From Site	Contact	NGR
Radon Potential -	Radon Potential - Radon Protection Measures				
	: No radon protective measures are necessary in the construction of new dwellings or extensions	A13NE (W)	0	1	312874 358195
Source:	British Geological Survey, National Geoscience Information Service				

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 21 of 37



### **Industrial Land Use**

Contemporary Trade Directory Entries  Name: Spanners Rhos St, Ruthin, Clwyd, LL15 1DY Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location Contemporary Trade Directory Entries  Name: Ruthin Community Hospital Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Active Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Ruthin Community Hospital Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location  Contemporary Trade Directory Entries  Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Gerage Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Gerage Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Connor The Viking Blacksmith Location: G2 Llanfair Road, Ruthin, Clwyd, LL15 1BU Cl	A13SE (S)  A13SE (S)  A13NW (W)	33 33 54	-	312844 358246 312893 358109 312893 358109
Location: Rhos St, Ruthin, Clwyd, LL15 1DY Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location: Contemporary Trade Directory Entries Name: Ruthin Community Hospital Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Active Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Ruthin Community Hospital Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: E G Atkinson & Co Location: Rhos St, Ruthin, Clwyd, LL15 1DU Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location  Contemporary Trade Directory Entries  70 Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Ceramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Clay Craft Location: Classification: Blacksmith S& Forgemasters	(NW) A13SE (S)  A13SE (S)  A13NW (W)	33	-	358246 312893 358109 312893
Name: Ruthin Community Hospital   Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS	A13SE (S)  A13NW (W)	33	-	358109 312893
Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Active Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Ruthin Community Hospital Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Rame: E G Atkinson & Co Location: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location  Contemporary Trade Directory Entries  Contemporary Trade Directory Entries  Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: Garage Kervices Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Clay Craft Location: Garagic Manufacturers, Supplies & Services Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Connor The Viking Blacksmith Location: G2 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters	A13SE (S)  A13NW (W)	33	-	358109 312893
Name: Ruthin Community Hospital Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries Name: E G Atkinson & Co Location: Rhos St, Ruthin, Clwyd, LL15 1DU Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location  Contemporary Trade Directory Entries  Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Hauffryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Ceramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Ceramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Blacksmiths & Forgemasters	A13NW (W)		-	
Location: Llanrhydd Street, Ruthin, Clwyd, LL15 1PS Classification: Hospitals Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: E G Atkinson & Co Location: Rhos St, Ruthin, Clwyd, LL15 1DU Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location  Contemporary Trade Directory Entries  Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Ceramic Manufacturers, Supplies & Services Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Contemporary T	A13NW (W)		-	
69 Name: E G Atkinson & Co Location: Rhos St, Ruthin, Clwyd, LL15 1DU Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location  Contemporary Trade Directory Entries  70 Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  70 Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  71 Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Geramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  71 Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters	(W)	54		1
Location: Rhos St, Ruthin, Clwyd, LL15 1DU Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned to the road within the address or location: Contemporary Trade Directory Entries  Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  71 Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Geramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  71 Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters	(W)	54		I
70 Name: Welch Group Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  70 Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  71 Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Geramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  71 Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters			-	312776 358218
Location: Moorfield Road, Duxford, Cambridge, Cambridgeshire, CB2 Classification: Garage Services  Status: Inactive Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Geramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters				
Contemporary Trade Directory Entries  Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Geramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters	22 4PS A13NW (N)	102	-	312818 358341
70 Name: Lloyd & Williams Location: Haulfryn, Ruthin, Clwyd, LL15 1HB Classification: Garage Services Status: Active Positional Accuracy: Manually positioned within the geographical locality  Contemporary Trade Directory Entries  71 Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Ceramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  71 Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters				
Contemporary Trade Directory Entries  Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Ceramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters	A13NW (N)	112	-	312816 358351
71 Name: Clay Craft Location: A, 61, Well Street, Ruthin, Clwyd, LL15 1AG Classification: Ceramic Manufacturers, Supplies & Services Status: Inactive Positional Accuracy: Automatically positioned to the address  Contemporary Trade Directory Entries  71 Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters				
Contemporary Trade Directory Entries  71 Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters	A13SW (W)	159	-	312678 358183
71 Name: Connor The Viking Blacksmith Location: 62 Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Blacksmiths & Forgemasters				
Positional Accuracy: Automatically positioned to the address	A13SW (W)	162	-	312692 358140
Contemporary Trade Directory Entries				
Name: King'S Ironmongers Location: 42, Well Street, Ruthin, Clwyd, LL15 1AW Classification: Hardware Status: Active Positional Accuracy: Automatically positioned to the address	A13SW (W)	205	-	312637 358161
Contemporary Trade Directory Entries				
72 Name: Anchor Garage Location: Llanfair Road, Ruthin, LL15 1BU Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A13SW (SW)	169	-	312707 358090
Contemporary Trade Directory Entries				
72 Name: White Bear Garage Location: 11, Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Garage Services Status: Active Positional Accuracy: Automatically positioned to the address	A13SW (SW)	185	-	312702 358066
Contemporary Trade Directory Entries				
72 Name: Well Equipped Location: 11, Llanfair Road, Ruthin, Clwyd, LL15 1BU Classification: Distribution Services Status: Inactive Positional Accuracy: Automatically positioned to the address	1	185	-	312702 358066



### **Industrial Land Use**

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
73	Contemporary Trad Name: Location: Classification: Status:	e Directory Entries Slaters Of Ruthin Ltd Well Street, Ruthin, Clwyd, LL15 1AF Car Dealers Inactive	A13NW (W)	214	-	312617 358200
	Positional Accuracy:  Contemporary Trad	Automatically positioned to the address  e Directory Entries				
74	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	Kootchi Koo Rhos Ial, Llanfair Road, Ruthin, Clwyd, LL15 1BY Children & Babywear - Manufacturers & Wholesalers Inactive Automatically positioned to the address	A13SW (SW)	263	-	312729 357926
75	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries The Garment Spa 29 Well St, Ruthin, Clwyd, LL15 1AF Dry Cleaners Inactive Manually positioned to the address or location	A13NW (W)	279	-	312550 358206
76	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Clwyd Army & Navy Stores 19, Well Street, Ruthin, Clwyd, LL15 1AE Leisure & Sportswear Manufacturers & Wholesalers Inactive Automatically positioned to the address	A12NE (W)	327	-	312501 358218
77	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Aroma Hut  3, Castle Mews, 8, Well Street, Ruthin, Clwyd, LL15 1AH Candle Manufacturers & Suppliers Inactive Automatically positioned to the address	A12NE (W)	389	-	312439 358221
78	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Mirage Ruthin Craft Centre, Lon Parcwr, Ruthin, LL15 1BB Jewellery Manufacturers & Repairers Inactive Manually positioned within the geographical locality	A18SW (NW)	455	-	312543 358589
78	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Bizarre Furniture  Unit 3, Ruthin Craft Centre, Lon Parcwr, Ruthin, Clwyd, LL15 1BB  Furniture Manufacturers - Home & Office  Inactive  Automatically positioned to the address	A18SW (NW)	459	-	312538 358591
78	Contemporary Trad Name: Location: Classification: Status:		A17SE (NW)	462	-	312519 358578
78	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Thomas Higginson Unit 11, Ruthin Craft Centre, Lon Parcwr, Ruthin, Clwyd, LL15 1BB Cabinet Makers Inactive Automatically positioned to the address	A17SE (NW)	470	-	312516 358586
78	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Liz Porter Unit 1, Ruthin Craft Centre, Lon Parcwr, Ruthin, Clwyd, LL15 1BB Picture & Picture Frame Renovating & Restoring Inactive Automatically positioned to the address	A17SE (NW)	477	-	312525 358603
79	Contemporary Trad Name: Location: Classification: Status:		A18SW (N)	498	-	312705 358721
80	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Fueltech The Bungalow,Upper Clwyd St, Ruthin, Clwyd, LL15 1HY Boilers - Servicing, Replacements & Repairs Inactive Manually positioned to the address or location	A12NE (W)	511	-	312318 358196



### **Industrial Land Use**

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Contemporary Trad	•				
81	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	Lovingly Made By Lyn 15 Clwyd Street, Ruthin, Clwyd, LL15 1HF Soft Furnishings - Manufacturers Inactive Automatically positioned to the address	A12NE (W)	534	-	312294 358257
	Contemporary Trad	e Directory Entries				
81	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	Hideaway 24, Clwyd Street, Ruthin, LL15 1HW Leather Garments & Products Active Automatically positioned to the address	A12NE (W)	576	-	312252 358243
	Contemporary Trad	e Directory Entries				
81	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	Fine Line Printing & Stationery Ltd 32, Clwyd Street, Ruthin, LL15 1HW Printers Active Automatically positioned to the address	A12NE (W)	598	1	312230 358229
	Contemporary Trad	e Directory Entries				
82	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	Huws Gray Building Materials Centre Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Builders' Merchants Active Automatically positioned to the address	A18SW (NW)	542	-	312548 358698
	Contemporary Trad	e Directory Entries				
83	Name: Location: Classification: Status: Positional Accuracy:	Swift Pest Control & Prevention Services 19, Llwyn Menlli, Ruthin, Clwyd, LL15 1RG Pest & Vermin Control Inactive Automatically positioned to the address	A9NW (SE)	597	-	313295 357689
	Contemporary Trade Directory Entries					
84	Name: Location: Classification: Status:	Fridges Direct Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ Refrigeration Equipment - Commercial Active Automatically positioned to the address	A18SW (NW)	612	-	312536 358772
		Contemporary Trade Directory Entries				
84	Name: Location: Classification: Status:	Mount Wright Ltd Unit 2, Lon Parcwr Industrial Estate, RUTHIN, Clwyd, LL15 1NJ Television & Video Manufacturers & Wholesalers Active Automatically positioned to the address	A18SW (NW)	630	-	312555 358802
	Contemporary Trad					
85	Name: Location: Classification: Status:	Auto Products Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Garage Services Inactive Automatically positioned to the address	A17SE (NW)	641	-	312474 358769
	Contemporary Trad	e Directory Entries				
86	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	Valley Arms Bolero Camp, Park Road, Ruthin, Clwyd, LL15 1NB Gunsmiths Active Automatically positioned to the address	A17SE (NW)	653	-	312246 358532
	Contemporary Trad	e Directory Entries				
87	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	R C Thomas 55, Bro Deg, Ruthin, Clwyd, LL15 1YQ Concrete Reinforcements Inactive Automatically positioned to the address	A8SE (S)	682	-	313045 357478
	Contemporary Trade Directory Entries					
88	Name: Location: Classification: Status: Positional Accuracy:	Delrue Bookbinders Mill Street, Ruthin, Clwyd, LL15 1HT Bookbinding & Equipment Inactive Manually positioned within the geographical locality	A12SW (W)	686	-	312155 358100
	,	,,				
88	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	Clean & Bright Flat 12, Felindre, Mill Street, Ruthin, Clwyd, LL15 1HL Cleaning Services - Domestic Active Automatically positioned to the address	A12SW (W)	715	-	312129 358088



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
89	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Gunn J C B Hen Lon Parcwr, Ruthin, Clwyd, LL15 1LY Plant & Machinery Repairs Active Automatically positioned to the address	A17SE (NW)	697	-	312335 358728
90	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Richard Williams Park Road, Ruthin, LL15 1NF Builders' Merchants Active Automatically positioned to the address	A12NW (NW)	704	-	312188 358528
91	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Patchwork Traditional Foods Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Food Products - Manufacturers Inactive Automatically positioned to the address	A17SE (NW)	721	-	312437 358841
91	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Swift Pest Control Unit 6, Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ Pest & Vermin Control Active Automatically positioned to the address	A17SE (NW)	721	-	312437 358840
91	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Gwyn Evans Lon Parcwr Ind Est, Ruthin, Clwyd, LL15 1NJ Road Haulage Services Inactive Manually positioned within the geographical locality	A17NE (NW)	742	-	312484 358892
91	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	Le Directory Entries Uproar Lon Parcwr Ind Est, Ruthin, Clwyd, LL15 1NJ Firework Stockists Inactive Manually positioned within the geographical locality	A17NE (NW)	743	-	312468 358884
91	Contemporary Trad Name: Location: Classification: Status:		A17NE (NW)	746	-	312446 358875
91	Contemporary Trad Name: Location: Classification: Status:		A17NE (NW)	749	-	312454 358884
92	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	Wrg Northweston Division Ion Parcwr, Ruthin, Clwyd, LL15 1NA Waste Disposal Services Inactive Manually positioned within the geographical locality	A12NW (W)	723	-	312105 358242
93	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entries Fluid Power Initiatives Ltd Industrial Unit, Llys Clwyd, Ffordd Celyn, Ruthin, LL15 1NJ Flow Measurement Systems - Manufacturers Active Automatically positioned to the address	A17SE (NW)	727	-	312405 358826
94	Contemporary Trad Name: Location: Classification: Status:	•	A17SE (NW)	761	-	312253 358734
94	Contemporary Trad Name: Location: Classification: Status:		A17SE (NW)	762	-	312253 358734



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
94	Contemporary Trade Directory Entries  Name: Al Cool Products Ltd Location: Birch House, Hen Lon Classification: Confectionery Manufac Status: Active Positional Accuracy: Automatically positione		A17SE (NW)	762	-	312253 358734
94	Contemporary Trade Directory Entries  Name: Ruthin Car Sales Location: Hen Lon Parcwr, Ruthi Classification: Car Dealers - Used  Status: Inactive  Positional Accuracy: Automatically positione	•	A17SE (NW)	762	-	312253 358734
95	Contemporary Trade Directory Entries  Name: A & D Coals Location: 76, Bro Deg, Ruthin, C Classification: Coal & Smokeless Fue Status: Inactive Positional Accuracy: Automatically positione	I Merchants & Distributors	A8SE (S)	770	-	313171 357425
96	Contemporary Trade Directory Entries  Name: Texaco Location: Park Road, Ruthin, Clv Classification: Petrol Filling Stations Status: Inactive Positional Accuracy: Manually positioned to	•	A12SW (W)	777	-	312053 358173
96	Contemporary Trade Directory Entries  Name: M R H Service Station Location: Service Station, Park F Classification: Petrol Filling Stations Status: Inactive Positional Accuracy: Automatically positione		A12SW (W)	778	-	312052 358173
96	Contemporary Trade Directory Entries  Name: B P Service Station Location: SERVICE STATION, P Classification: Petrol Filling Stations Status: Active Positional Accuracy: Automatically positione	ARK ROAD, RUTHIN, LL15 1NB	A12SW (W)	778	-	312052 358173
96	Contemporary Trade Directory Entries  Name: Texaco Location: Service Station, Park F Classification: Petrol Filling Stations Status: Inactive Positional Accuracy: Automatically positione	Road, Ruthin, Clwyd, LL15 1NB	A12SW (W)	780	-	312051 358173
96	Contemporary Trade Directory Entries  Name: Malthurst Field Group S Location: Park Road, Ruthin, Clv Classification: Petrol Filling Stations Status: Inactive  Positional Accuracy: Automatically positione	<sub>/</sub> yd, LL15 1NB	A12SW (W)	780	-	312051 358173
96	Contemporary Trade Directory Entries  Name: A Touch Of Class Location: 1, Mwrog Street, Ruthin Classification: Dry Cleaners Status: Active  Positional Accuracy: Automatically positione	n, Clwyd, LL15 1LB	A12SW (W)	793	-	312042 358131
97	Contemporary Trade Directory Entries  Name: M J Autos Location: Lon Parcwr Industrial E Classification: Garage Services Status: Inactive Positional Accuracy: Automatically positione	state, Ruthin, Clwyd, LL15 1NJ d to the address	A18NW (N)	777	-	312566 358968
97	Contemporary Trade Directory Entries  Name: Patchwork Pate Location: 17, Lon Parcwr Industr Classification: Food Products - Manuf Status: Active Positional Accuracy: Automatically positione		A18NW (N)	777	-	312566 358968
98	Contemporary Trade Directory Entries  Name: Harrison Machinery Location: Hen Lon Parcwr, Ruthi Classification: Agricultural Machinery Status: Active Positional Accuracy: Automatically positione	n, LL15 1NA - Sales & Service	A17SE (NW)	779	-	312314 358820



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Contemporary Trad	e Directory Entries				
98	Name: Location: Classification: Status:	Redstone Subaru Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ Car Dealers Active Automatically positioned to the address	A17SE (NW)	802	-	312313 358850
	Contemporary Trad	e Directory Entries				
98	Name: Location: Classification: Status:	Owen Commercials UNit 11 Clwyd Yard,Hen Lon Parcwr, Ruthin, Clwyd, LL15 1LY Commercial Vehicle Bodybuilders & Repairers Inactive Manually positioned to the road within the address or location	A17SE (NW)	813	-	312301 358854
	Contemporary Trad	e Directory Entries				
99	Name: Location: Classification: Status:	Salisbury Garden & Hire Services Unit 9 Hen Lon Parcwr, Ruthin, Clwyd, LL15 1NA Lawnmowers & Garden Machinery - Sales & Service Active Manually positioned to the address or location	A17SE (NW)	782	-	312275 358788
	Contemporary Trad	e Directory Entries				
99	Name: Location: Classification: <b>Status:</b> Positional Accuracy:	Harrison Machinery Ltd Hen Lon Parcwr, Ruthin, Clwyd, LL15 1NA Plant & Machinery Repairs Inactive Manually positioned within the geographical locality	A17SE (NW)	794	-	312275 358805
	Contemporary Trad	e Directory Entries				
99	Name: Location: Classification: Status: Positional Accuracy:	Bartleys Tyres Hen Lon Parcwr, Ruthin, Clwyd, LL15 1NA Tyre Dealers Active Manually positioned within the geographical locality	A17SE (NW)	803	-	312261 358803
100	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	T & K Electronics Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Domestic Appliances - Servicing, Repairs & Parts Inactive Automatically positioned in the proximity of the address	A17SE (NW)	785	-	312359 358864
	Contemporary Trad					
100	Name: Location: Classification: Status:	Auto Mark Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Garage Services Inactive Automatically positioned to the address	A17NE (NW)	804	-	312393 358911
	Contemporary Trad	* '				
100	Name: Location: Classification: Status:	W M System 3 Ffordd Celyn, Ruthin, Clwyd, LL15 1NJ Commercial Vehicle Servicing, Repairs, Parts & Accessories Active Manually positioned to the address or location	A17NE (NW)	807	-	312355 358889
	Contemporary Trad	· · · · · · · · · · · · · · · · · · ·				
100	Name: Location: Classification: Status:	Edge Ltd Watergate House, Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ Cleaning Materials & Equipment Active Automatically positioned to the address	A17NE (NW)	807	-	312355 358889
100	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  M W S  Watergate House, Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ  Vacuum Cleaners, Industrial & Commercial - Repairs & Servicing  Active  Automatically positioned to the address	A17NE (NW)	807	-	312355 358889
	Contemporary Trad					
100	Name: Location: Classification: Status:	Ruthin Body Repairs Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Car Body Repairs Inactive Automatically positioned to the address	A17NE (NW)	843	-	312342 358923
	Contemporary Trad	* '				
101	Name: Location: Classification: Status:	Bellarion Lon Parcwr Ind Est, Ruthin, Clwyd, LL15 1NJ Car Accessories Manufacturers Inactive Manually positioned within the geographical locality	A17NE (NW)	805	-	312438 358939



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
101	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  The Garment Spa Unit 1, Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Dry Cleaners Active Automatically positioned to the address	A17NE (NW)	806	-	312438 358939
102	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Ruthin M O T Unit 14, Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ Mot Testing Centres Inactive Automatically positioned to the address	A17SE (NW)	808	-	312235 358783
102	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Ruthin M O T Centre Unit 14, Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ Mot Testing Centres Inactive Automatically positioned to the address	A17SE (NW)	808	-	312235 358783
102	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Richard Jones & Co The Coal Yard, Hen Lon Parcwr, Ruthin, Clwyd, LL15 1NA Coal & Smokeless Fuel Merchants & Distributors Active Automatically positioned to the address	A17SE (NW)	837	-	312207 358796
102	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Lewis & Hunter Contracting  Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NA  Asphalt & Coated Macadam Laying Contractors  Active  Manually positioned within the geographical locality	A17SE (NW)	837	-	312207 358796
102	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  R D Jones & Son The Coal Yard, Hen Lon Parcwr, Ruthin, Clwyd, LL15 1NA Road Haulage Services Inactive Automatically positioned to the address	A17SE (NW)	837	-	312207 358796
103	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Automark  Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ  Garage Services  Active  Manually positioned within the geographical locality	A17NE (NW)	815	-	312428 358945
103	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Wynnstay Unit 1-2,Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Pet Foods & Animal Feeds Active Manually positioned within the geographical locality	A17NE (NW)	815	-	312428 358945
103	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  D & S Motors  Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ  Garage Services  Inactive  Automatically positioned to the address	A17NE (NW)	816	-	312411 358935
103	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Red Dragon Dispense  Unit 9, Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ  Soft Drinks - Manufacturers  Active  Automatically positioned to the address	A17NE (NW)	838	-	312380 358943
103	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Morgans Of Ruthin 8, Lon Parcwr Business Centre, Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Builders' Merchants Active Automatically positioned to the address	A17NE (NW)	838	-	312380 358943



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
103	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Alpha Flex Uk Ltd  Unit 10, Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ  Seal & Joint Manufacturers  Inactive  Automatically positioned to the address	A17NE (NW)	843	-	312399 358960
103	Contemporary Trad Name: Location: Classification: Status:	··	A17NE (NW)	843	-	312399 358960
104	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Dragon Tyres Services Mwrog Street, Ruthin, Clwyd, LL15 1LB Tyre Dealers Active Automatically positioned to the address	A12SW (W)	855	-	311984 358096
105	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  R M Jones Clwydfro Business Centre, Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Joinery Manufacturers Inactive Automatically positioned to the address	A17NE (NW)	866	-	312460 359018
105	Contemporary Trad Name: Location: Classification: Status:		A17NE (NW)	866	-	312459 359018
105	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Clothing Design Company,The Unit 8, Clwydfro Business Centre, Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Clothing & Fabrics - Manufacturers Inactive Automatically positioned to the address	A17NE (NW)	872	-	312454 359023
105	Contemporary Trad Name: Location: Classification: Status:	··	A17NE (NW)	872	-	312454 359023
105	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  M P I Campers Unit 7b, Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Caravans - Servicing & Repairs Active Automatically positioned to the address	A17NE (NW)	877	-	312489 359044
105	Contemporary Trad Name: Location: Classification: Status:		A17NE (NW)	877	-	312489 359044
105	Contemporary Trad Name: Location:  Classification: Status: Positional Accuracy:	e Directory Entries Impress Hydraulic Services Unit 9, Clwydfro Business Centre, Lon Parcwr Industrial Estate, Ruthin, Clwyd, LL15 1NJ Hydraulic Engineers Inactive Automatically positioned to the address	A17NE (NW)	882	-	312425 359018
105	Contemporary Trad Name: Location: Classification: Status:		A17NE (NW)	882	-	312449 359030

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 29 of 37



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
105	Contemporary Trad Name: Location:	e Directory Entries Ruthin Laundry Unit 4, Clwydfro Business Centre, Lon Parcwr Industrial Estate, Ruthin, LL15 1NJ	A17NE (NW)	888	-	312449 359038
	Classification: <b>Status:</b> Positional Accuracy:	Laundries & Launderettes Inactive Automatically positioned to the address				
106	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries It Office Furniture Ltd Min y Clwyd, Hen Lon Parcwr, Ruthin, LL15 1NA Office Furniture & Equipment Inactive Automatically positioned to the address	A17NE (NW)	875	-	312276 358914
107	Contemporary Trad Name: Location: Classification: Status:	**	A17NE (NW)	896	-	312397 359020
108	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  Moto-R Hen Lon Parcwr, Ruthin, LL15 1LY Garage Services Active Automatically positioned to the address	A17NE (NW)	904	-	312327 358988
109	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Glan Clwyd Garage Mwrog Street, Ruthin, LL15 1LB Garage Services Active Automatically positioned to the address	A12SW (W)	935	-	311920 358009
110	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries  J M Rennie Ltd Depot, Hen Lon Parcwr, Ruthin, Clwyd, LL15 1NA Concrete & Mortar Ready Mixed Active Automatically positioned to the address	A17NW (NW)	1000	-	312151 358972
111	Fuel Station Entries Name: Location: Brand: Premises Type: Status: Positional Accuracy:	Slaters Of Ruthin Ltd Well Street , , Ruthin, Denbighshire, LL15 1AF OBSOLETE Not Applicable Obsolete Automatically positioned to the address	A13NW (W)	214	-	312617 358200
112	Fuel Station Entries Name: Location: Brand: Premises Type: Status: Positional Accuracy:	Mfg Ruthin Park Road , , Denbigh, Denbighshire, LL15 1NB Bp Petrol Station Open Automatically positioned to the address	A12SW (W)	780	-	312051 358173

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 30 of 37



## **Sensitive Land Use**

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Ancient Woodland					
113	Name: Reference: Area(m²): Type:	Not Supplied 37228 9911.79 Restored Ancient Woodland Site	A12SE (SW)	512	2	312397 357944
	Ancient Woodland					
114	Name: Reference: Area(m²): Type:	Not Supplied 37229 6608.13 Restored Ancient Woodland Site	A12SE (W)	649	2	312218 358011
	Environmentally S	ensitive Areas				
115	Name: Multiple Areas: Total Area (m2): Source:	Clwydian Range (decommissioned) N 278715136 The National Assembly for Wales, GI Services (Department of Planning & Countryside)	A13NE (W)	0	6	312874 358195

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 31 of 37



Agency & Hydrological	Version	Update Cycle
Contaminated Land Register Entries and Notices  Denbighshire County Council - Public Protection Department  Natural Resources Wales	January 2015 June 2020	Annual Rolling Update Annually
<b>Discharge Consents</b> Environment Agency - Welsh Region Natural Resources Wales	August 2014 November 2020	Quarterly Quarterly
Enforcement and Prohibition Notices Environment Agency - Welsh Region	March 2013	Annual Rolling Update
Integrated Pollution Controls Environment Agency - Welsh Region	October 2008	Variable
Integrated Pollution Prevention And Control Natural Resources Wales Environment Agency - Welsh Region	November 2020 October 2020	Quarterly Quarterly
Local Authority Integrated Pollution Prevention And Control  Denbighshire County Council - Environmental Health Department	March 2013	Variable
Local Authority Pollution Prevention and Controls  Denbighshire County Council - Environmental Health Department  Local Authority Pollution Prevention and Control Enforcements	December 2014	Annual Rolling Update
Denbighshire County Council - Environmental Health Department  Nearest Surface Water Feature	December 2014	Variable
Ordnance Survey	October 2020	
Pollution Incidents to Controlled Waters Environment Agency - Welsh Region	December 1998	Not Applicable
Prosecutions Relating to Authorised Processes Environment Agency - Welsh Region Natural Resources Wales	March 2013 March 2013	Annual Rolling Update Annual Rolling Update
Prosecutions Relating to Controlled Waters Environment Agency - Welsh Region Natural Resources Wales	March 2013 March 2013	Annual Rolling Update Annual Rolling Update
Registered Radioactive Substances Natural Resources Wales Environment Agency - Welsh Region	January 2015 June 2016	Annually
River Quality Environment Agency - Head Office	November 2001	Not Applicable
River Quality Chemistry Sampling Points Environment Agency - Head Office	July 2012	Annually
Substantiated Pollution Incident Register Natural Resources Wales Environment Agency Wales - North Area	November 2020 October 2020	Quarterly Quarterly
<b>Water Abstractions</b> Natural Resources Wales Environment Agency - Welsh Region	November 2020 October 2020	Quarterly Quarterly
Water Industry Act Referrals Natural Resources Wales Environment Agency - Welsh Region	November 2020 October 2017	Quarterly Quarterly
Groundwater Vulnerability Map Natural Resources Wales	June 2018	As notified
Bedrock Aquifer Designations Natural Resources Wales	January 2018	Annually
Superficial Aquifer Designations Natural Resources Wales	January 2018	Annually

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 32 of 37



Agency & Hydrological	Version	Update Cycle
Source Protection Zones		
Natural Resources Wales	November 2016	Annual Rolling Update
Extreme Flooding from Rivers or Sea without Defences		
Natural Resources Wales	August 2018	Quarterly
Flooding from Rivers or Sea without Defences		
Natural Resources Wales	September 2020	Quarterly
Areas Benefiting from Flood Defences		
Natural Resources Wales	November 2019	Quarterly
Flood Water Storage Areas		
Natural Resources Wales	August 2019	Quarterly
Flood Defences		
Natural Resources Wales	November 2019	Quarterly
OS Water Network Lines		
Ordnance Survey	September 2020	Quarterly
BGS Groundwater Flooding Susceptibility		
British Geological Survey - National Geoscience Information Service	May 2013	Annually
Waste	Version	Update Cycle
BGS Recorded Landfill Sites		
British Geological Survey - National Geoscience Information Service	June 1996	Not Applicable
Historical Landfill Sites		
Natural Resources Wales	July 2017	Quarterly
Integrated Pollution Control Registered Waste Sites		
Environment Agency - Welsh Region	October 2008	Not Applicable
Licensed Waste Management Facilities (Landfill Boundaries)		
Environment Agency Wales - North Area	October 2020	Quarterly
Natural Resources Wales	October 2020	Quarterly
Licensed Waste Management Facilities (Locations)		
Natural Resources Wales	November 2020	Quarterly
Environment Agency Wales - North Area	October 2020	Quarterly
Local Authority Landfill Coverage		
Denbighshire County Council - Environmental Health Department	May 2000	Not Applicable
Local Authority Recorded Landfill Sites		
Denbighshire County Council - Environmental Health Department	May 2000	Not Applicable
Registered Landfill Sites		
Environment Agency Wales - North Area	March 2003	Not Applicable
Registered Waste Transfer Sites		
Environment Agency Wales - North Area	March 2003	Not Applicable
Registered Waste Treatment or Disposal Sites		
	1	Not Applicable

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 33 of 37



Hazardous Substances	Version	Update Cycle
Control of Major Accident Hazards Sites (COMAH)	A = :!! 2040	Di Americalli.
Health and Safety Executive	April 2018	Bi-Annually
Explosive Sites Health and Safety Executive	March 2017	Annually
Notification of Installations Handling Hazardous Substances (NIHHS)		
Health and Safety Executive	November 2000	Not Applicable
Planning Hazardous Substance Enforcements Denbighshire County Council - Planning Department	February 2016	Variable
Planning Hazardous Substance Consents	,	
Denbighshire County Council - Planning Department	February 2016	Variable
Geological	Version	Update Cycle
BGS 1:625,000 Solid Geology		
British Geological Survey - National Geoscience Information Service	January 2009	Not Applicable
BGS Recorded Mineral Sites		
British Geological Survey - National Geoscience Information Service	November 2020	Bi-Annually
CBSCB Compensation District		
Cheshire Brine Subsidence Compensation Board (CBSCB)	August 2011	Not Applicable
Coal Mining Affected Areas		
The Coal Authority - Property Searches	March 2014	Annual Rolling Updat
Mining Instability		
Ove Arup & Partners	October 2000	Not Applicable
Non Coal Mining Areas of Great Britain		
British Geological Survey - National Geoscience Information Service	May 2015	Not Applicable
Potential for Collapsible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	April 2020	Annually
Potential for Compressible Ground Stability Hazards		,
British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Ground Dissolution Stability Hazards		
British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Landslide Ground Stability Hazards		
British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Running Sand Ground Stability Hazards		
British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Shrinking or Swelling Clay Ground Stability Hazards		
British Geological Survey - National Geoscience Information Service	January 2019	Annually
Radon Potential - Radon Affected Areas		
British Geological Survey - National Geoscience Information Service	July 2011	Annually
Radon Potential - Radon Protection Measures		
British Geological Survey - National Geoscience Information Service	July 2011	Annually
Industrial Land Use	Version	Update Cycle
Contemporary Trade Directory Entries		
Thomson Directories	October 2020	Quarterly
Fuel Station Entries		
Catalist Ltd - Experian	September 2020	Quarterly
Gas Pipelines National Grid	September 2020	
	September 2020	
Underground Electrical Cables	A.v.av.ct 0000	
National Grid	August 2020	

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 34 of 37



Sensitive Land Use	Version	Update Cycle
Ancient Woodland		
Natural Resources Wales	August 2018	Bi-Annually
Areas of Adopted Green Belt		
Denbighshire County Council	June 2020	As notified
Areas of Unadopted Green Belt		
Denbighshire County Council	June 2020	As notified
Areas of Outstanding Natural Beauty		
Natural Resources Wales	June 2019	Bi-Annually
Environmentally Sensitive Areas		
The National Assembly for Wales - GI Services (Department of Planning & Countryside)	January 2017	
Forest Parks		
Forestry Commission	April 1997	Not Applicable
Local Nature Reserves		
Denbighshire County Council	August 2018	Bi-Annually
Marine Nature Reserves		
Natural Resources Wales	August 2018	Bi-Annually
National Nature Reserves		
Natural Resources Wales	June 2019	Bi-Annually
National Parks		
Natural Resources Wales	August 2018	Annually
Nitrate Vulnerable Zones		
Natural Resources Wales	July 2019	Bi-Annually
The National Assembly for Wales - GI Services (Department of Planning & Countryside)	October 2005	
Ramsar Sites		
Natural Resources Wales	July 2019	Bi-Annually
Sites of Special Scientific Interest		
Natural Resources Wales	March 2020	Bi-Annually
Special Areas of Conservation		
Natural Resources Wales	August 2020	Bi-Annually
Special Protection Areas		
Natural Resources Wales	August 2018	Bi-Annually

Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 35 of 37





A selection of organisations who provide data within this report

Data Supplier	Data Supplier Logo
Ordnance Survey	Maga durin
Environment Agency	Linvironment.
Scottish Environment Protection Agency	SEPÂ
The Coal Authority	The Coal Authority
British Geological Survey	British Geological Survey
Centre for Ecology and Hydrology	Centre for Ecology & Hydrology
Natural Resources Wales	Cyfried Britania (all
Scottish Natural Heritage	SCOTTISH MATURAL HERITOGE WYCES
Natural England	ENGLAND
Public Health England	Public Health England
Ove Arup	ARUP
Stantec UK Ltd	Stantec





## **Useful Contacts**


Contact	Name and Address	Contact Details	
1	British Geological Survey - Enquiry Service  British Geological Survey, Environmental Science Centre, Keyworth, Nottingham, Nottinghamshire, NG12 5GG	Telephone: 0115 936 3143 Fax: 0115 936 3276 Email: enquiries@bgs.ac.uk Website: www.bgs.ac.uk	
2	Natural Resources Wales Ty Cambria, 29 Newport Road, Cardiff, CF24 0TP	Telephone: 0300 065 3000 Email: enquiries@naturalresourceswales.gov.uk	
3	Denbighshire County Council - Environmental Health Department Caledfryn, Smithfield, Denbigh, Denbighshire, LL16 3RJ	Telephone: 01824 706000 Fax: 01824 705026 Website: www.denbighshire.gov.uk	
4	Environment Agency - National Customer Contact Centre (NCCC) PO Box 544, Templeborough, Rotherham, S60 1BY	Telephone: 03708 506 506 Email: enquiries@environment-agency.gov.uk	
5	Ordnance Survey Adanac Drive, Southampton, Hampshire, SO16 0AS	Telephone: 03456 05 05 05 Email: customerservices@ordnancesurvey.co.uk Website: www.ordnancesurvey.gov.uk	
6	The National Assembly for Wales - GI Services (Department of Planning & Countryside)  Yr Hen Ysgol Gymraeg, Alexandria Road, Aberystwyth, Ceredigion, SY23 1LD	Telephone: 02920 825111 Website: www.wales.gov.uk	
-	Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards Chilton, Didcot, Oxfordshire, OX11 0RQ	Telephone: 01235 822622 Fax: 01235 833891 Email: radon@phe.gov.uk Website: www.ukradon.org	
-	Landmark Information Group Limited Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9952 Fax: 0844 844 9951 Email: customerservices@landmarkinfo.co.uk Website: www.landmarkinfo.co.uk	


Please note that the Environment Agency / Natural Resources Wales / SEPA have a charging policy in place for enquiries.


Order Number: 270678250\_1\_1 Date: 16-Dec-2020 rpr\_ec\_datasheet v53.0 A Landmark Information Group Service Page 37 of 37

































Registered Office: InTec, Parc Menai, Bangor, Gwynedd, LL57 4FG

**Tel:** 01248 672666 **Fax:** 01248 672601


**Email:** contact@caulmert.com **Web:** www.caulmert.com

## **Historical Mapping Legends**

## **Ordnance Survey County Series 1:10,560** College (1995) Reads (1995) L Marsh Mixed Wess Depiduous Brindragoot Rough Pastura. Lurze Amba dendies Importmetrical 1 dwichwaler. Station Sile of Arliqui ⊸-Beredi Mara Pump Guide Foet, Well, Spring. Signal Divid Boundary Piet. -**285** Surface Level instrumental $\dots_{n-1,n^{d-1}}\dots_n$ Sincle reci Compan Comput -----Million Ruads Jreferond Figure 5 anken 5 acc Rasad Road Railway over Rober division Falluge River Tao-I Crossing -Roed av⊸r Notice to the County Edundary (Geographical) County & Craft Rerich Boundary Administrative County & D.M. Parish Beundary County Berough Boundary (Lingkind) Co Poro Esty County Burgh Bornowy (Spyllane) Co Ruich ace Rural Castrict Education ΠD C-d<sub>T</sub>.

orro - - - Chi Perien Borncera.

### Ordnance Survey Plan 1:10,000



Guice Post

MI / From

Mile Stone

Æ

Talephone Call Dox

Telephone Call Port

TOP

#### 1:10,000 Raster Mapping

	Cravel 3i	$(\frac{3\sqrt{3}\sqrt{3}\sqrt{3}}{2\sqrt{3}})$	Refuse tip or slag heap
	Rad:		5:k r-s:eller: r
$\frac{\frac{N}{2}}{\frac{N}{2}}\frac{\frac{N}{2}}{\frac{N}{2}}\frac{N}{2}\frac{N}{2}$	Boulders		Boulders (scallered)
$\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{$	Shingle		Vikid
(Said)	Sand	\$\$2(\$)	Send 3i
Winners.	flor-e	Proposition ACHEORS	Tablef c <b>iff</b>
	Sens al celal		Und⊷ground ⊲elei 
	Coethead celei		Матом да <b>цре</b> гамем
<del></del>	Multi-track reliwey		Single track railway
	County boundary (England only) District Hailera		Civil, parish an community bouncary
	Heingori en Looker Boroogle Journlary	<del>-</del>	Constituency boundary
con and	Area of was sent vegetation	00 Pd	Non-connectus trees
	Noneo ariferiors hess (soar ened)	t (2)	Conterous trees
2.	Contrer bus frees (spattered)	Ω	Pasilianec Iree
5 e 0 0	Onesid	9 4	Coopios or Celiere
ot.	Rough Grasskard		Health
0 to	Serus	ette Miss	Worsh, Sail Worsh or Reeds
P.	Water feature	**************************************	Еренияе⊲
M4593)	Maen nign water (eor ngs)	MAXAS)	Mesin kwi waran (apringa)
	Tel-plone-line (where sloven)		Liestrony transmission line (with poles)
L LMTZAJAPI	Bonen mark (where shown)	۵	Triangulation stallari
15.7	Point feature (e.g. Guide Posti of Mile Stone)	K	Prylon, fland stack anlighting tower
	Site of (actiquity)		Gle-o-licuser
	General Building		importani Bulking


# **Envirocheck**

LANDMARK INFORMATION GROUP

#### **Historical Mapping & Photography included:**

Mapping Type	Scale	Date	Pg
Denbighshire	1:10,560	1879	2
Denbighshire	1:10,560	1900	3
Denbighshire	1:10,560	1914	4
Denbighshire	1:10,560	1938 - 1953	5
Denbighshire	1:10,560	1953	6
Ordnance Survey Plan	1:10,000	1963	7
Ordnance Survey Plan	1:10,000	1975	8
Ordnance Survey Plan	1:10,000	1993	9
10K Raster Mapping	1:10,000	2000	10
Street View	Variable		11

## **Historical Map - Slice A**



#### **Order Details**

Order Number: 270678250\_1\_1 Customer Ref:

National Grid Reference: 312870, 358200 Slice:

0.55 Site Area (Ha): Search Buffer (m): 1000


#### **Site Details**

19, Rhos Street, RUTHIN, LL15 1DU



0844 844 9952 0844 844 9951

A Landmark Information Group Service v50.0 16-Dec-2020 Page 1 of 11



LANDMARK INFORMATION GROUP'


### Denbighshire

## Published 1879


## Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840's. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940's, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

#### Map Name(s) and Date(s)



#### **Historical Map - Slice A**



#### **Order Details**

Order Number: 270678250\_1\_1 Customer Ref: 4865

National Grid Reference: 312870, 358200

Slice: A

Site Area (Ha): 0.55 Search Buffer (m): 1000


#### **Site Details**

19, Rhos Street, RUTHIN, LL15 1DU



0844 844 9952 :: 0844 844 9951 b: www.envirocheck.co.uk

A Landmark Information Group Service v50.0 16-Dec-2020 Page 2 of 11



LANDMARK INFORMATION GROUP'


### **Denbighshire**

## Published 1900


## Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840's. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940's, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

#### Map Name(s) and Date(s)



#### **Historical Map - Slice A**



#### **Order Details**

Order Number: 270678250\_1\_1

Customer Ref: 4865

National Grid Reference: 312870, 358200

Slice:

Site Area (Ha): 0.55 Search Buffer (m): 1000


#### **Site Details**

19, Rhos Street, RUTHIN, LL15 1DU

Landmark

el: 0844 844 9952 ax: 0844 844 9951 /eb: www.enviroche


A Landmark Information Group Service v50.0 16-Dec-2020 Page 3 of 11



LANDMARK INFORMATION GROUP'

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840's. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940's, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every

#### Map Name(s) and Date(s)



270678250\_1\_1


National Grid Reference: 312870, 358200

0.55

19, Rhos Street, RUTHIN, LL15 1DU

0844 844 9951 www.envirocheck.co.uk

A Landmark Information Group Service v50.0 16-Dec-2020 Page 4 of 11




LANDMARK INFORMATION GROUP'

### **Denbighshire**


## Published 1938 - 1953 Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840's. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940's, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

### Map Name(s) and Date(s)



#### **Historical Map - Slice A**



#### **Order Details**

Order Number: 270678250\_1\_1

Customer Ref: 4865

National Grid Reference: 312870, 358200

e:

Site Area (Ha): 0.55 Search Buffer (m): 1000


**Site Details** 


19, Rhos Street, RUTHIN, LL15 1DU





l: 0844 844 9952 x: 0844 844 9951 eb: www.envirocheck

A Landmark Information Group Service v50.0 16-Dec-2020 Page 5 of 11










LANDMARK INFORMATION GROUP'

## **Ordnance Survey Plan** Published 1993 Source map scale - 1:10,000

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840's. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940's, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every



#### **Historical Map - Slice A**




270678250\_1\_1


National Grid Reference: 312870, 358200

19, Rhos Street, RUTHIN, LL15 1DU

0844 844 9951


A Landmark Information Group Service v50.0 16-Dec-2020 Page 9 of 11





## **Historical Mapping Legends**

### **Ordnance Survey County Series and** Ordnance Survey Plan 1:2,500




County Burgh Boundary (Spottand). Corburgh Say 37° BS - Boundary Yorkon Stoner Policy Call Box A dis Road FP. 115 B.B.Records by Police B.PSignal Prod Foor Full ge m. 31.80 Powr Firth Spring Telephone 3:11 Ross du de Post a Boses Trough N M Stone West. MFMR . Morning Post or Pung.

County Barbugh Baundary (England)

Corbord, Say.

Ordnance Survey Plan, Additional SIMs and Large-Scale National Grid Data 1:2,500 and **Supply of Unpublished Survey Information** 1:2,500 and 1:1,250




Liedingly Transmission Line

Emtrance

County Boundary (Scographical). County & Civil Parish Boundary. Civil Parish Boundary. Admin. County or County Feet. Bouncary. London Berough Beundary. Sync-4 herking paid where houndary. она в горольтория.

31	C-erik.es	r	Piller, Policion Post
32 PA	Эрипсим Роман Этоги	Fr.	Four@fire
Cn C	Capatan Crans	r=	Public Conventence
ulig	21 m rwy	44	P. Mic House
D-n	Jindang repartan	F:	Print
<b>3</b> P	Flooricity Of Lener Port	99 S Fr	Agran Forcer Pridee
745	"h+ Abort Piller	57 SL	Signal Teater Light
: P	"e-or: 31 dg s	5:r	S:do:
94 94	feat Bridge Golde You,	Ser Tk	Soring Tankor <sup></sup> reck
=	=		-
=	Quide Pou.	Te	Tank or Track
92 1	Galde Pou. Norenbort tydreulic	Tk 198	Tank of Track Tylophone Syll Sex
92 1 13	Galde Poul. Typranbort tydraulic awa Coossing	T4 108 TEP	Tank or Track  It ophone Sv I Sex  Telephone Cell Poet
92 1 1.3 <b>NH</b>	Garde Poul hydrauthorf tydrautho was Construg Yushicke	Ts 198 TEN	Tankor/Pack Taluphone WallSox Talaphone Call Post Yough

## 1:1,250



•		
CA: Demecke	F	Piller, Polision Post
Эту Эттик	PC	Powtoffice
Cercia De nervira	r=	Public Conventence
Chy Chimney	r=	Гитр
Cla Sinta 1	Pag Sta	Pumping Station
Dismital Ray — Chartenided Fishway	r <del>u</del>	Micco Moistet
DiGeniSte - Electricity Generating Similar	Sawaga Pp	rg Sile - Severge Pri op og Stado
diP distancily PM / PM u	88.881	Signal Service brings
Ci Sup Sie - Decripty Sup Siedon	8P. BL	Signal Postor Jage I
F3 FMcBcd	Spr	Spring
Po JD Po - Pourrain i Orink og Pro	7	Terk or Track
Ans Gov SawWhite Compound	-	Transport
CVO Guy Covernor	77 <b>0 P</b> p	We diffur p
CP Guide Poul	#PPUWIT	<b>Makin Homb Wilder Top</b>
MH Youliek	Why	Works from the gordine
MP NS - Villa Post of Villa Stone	H	Wall

Баловоу песнопрауше-4 (посно песно

н жиув неринг от уровне рийн ог угоож


# **Envirocheck**

LANDMARK INFORMATION GROUP

#### **Historical Mapping & Photography included:**

Mapping Type	Scale	Date	Pg
Denbighshire	1:2,500	1875	2
Denbighshire	1:2,500	1900	3
Denbighshire	1:2,500	1912	4
Ordnance Survey Plan	1:2,500	1969	5
Additional SIMs	1:2,500	1969 - 1986	6
Ordnance Survey Plan	1:2,500	1975 - 1984	7
Additional SIMs	1:2,500	1984 - 1988	8
Additional SIMs	1:2,500	1988	9
Large-Scale National Grid Data	1:2,500	1994	10
Large-Scale National Grid Data	1:2,500	1996	11

### **Historical Map - Segment A13**



#### **Order Details**

Order Number: 270678250\_1\_1 Customer Ref: National Grid Reference: 312870, 358200 Slice: Α

0.55 Site Area (Ha): Search Buffer (m): 100


#### **Site Details**


19, Rhos Street, RUTHIN, LL15 1DU





0844 844 9952 0844 844 9951

A Landmark Information Group Service v50.0 16-Dec-2020 Page 1 of 11










LANDMARK INFORMATION GROUP'

## Ordnance Survey Plan Published 1969


### Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840's. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

### Map Name(s) and Date(s)



### **Historical Map - Segment A13**



#### **Order Details**

Order Number: 270678250\_1\_1

Customer Ref: 4865 National Grid Reference: 312870, 358200

Slice: A

Site Area (Ha): 0.55 Search Buffer (m): 100


#### Site Details


19, Rhos Street, RUTHIN, LL15 1DU



el: 0844 844 9952 xx: 0844 844 9951 eb: www.envirocheck.co.uk

A Landmark Information Group Service v50.0 16-Dec-2020 Page 5 of 11






LANDMARK INFORMATION GROUP'

## **Ordnance Survey Plan** Published 1975 - 1984


## Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840's. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

### Map Name(s) and Date(s)



### **Historical Map - Segment A13**



#### **Order Details**

Order Number: 270678250\_1\_1 Customer Ref:

National Grid Reference: 312870, 358200

Site Area (Ha): Search Buffer (m):


#### **Site Details**


19, Rhos Street, RUTHIN, LL15 1DU




0844 844 9951 www.envirocheck.co.uk

A Landmark Information Group Service v50.0 16-Dec-2020 Page 7 of 11








LANDMARK INFORMATION GROUP'

## **Large-Scale National Grid Data** Published 1994


Source map scale - 1:2,500

'Large Scale National Grid Data' superseded SIM cards (Ordnance Survey's 'Survey of Information on Microfilm') in 1992, and continued to be produced until 1999. These maps were the fore-runners of digital mapping and so provide detailed information on houses and roads, but tend to show less topographic features such as vegetation. These maps were produced at both 1:2,500 and 1:1,250 scales.

### Map Name(s) and Date(s)



#### **Historical Map - Segment A13**



270678250\_1\_1 Customer Ref: National Grid Reference: 312870, 358200

19, Rhos Street, RUTHIN, LL15 1DU



0844 844 9951 www.envirocheck.co.uk

A Landmark Information Group Service v50.0 16-Dec-2020 Page 10 of 11

